

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
200 Rio Brazos Road, Aztec, NM 87410
District IV
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nHAP1408436341

Name of Company		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
COG OPERATING LLC 229137		Contact	Robert McNeill		
Address 600 West Illinois Avenue, Midland, TX 79701		Telephone No.	432-230-0077		
Facility Name Bragg 10 Fee #001H		Facility Type	Tank Battery		
Surface Owner Private		Mineral Owner	Lease No. (API#) 30-015-41462		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	10	19S	26E					Eddy

Latitude 32.66828 Longitude 104.37720

NATURE OF RELEASE

Type of Release Oil	Volume of Release 55bbls	Volume Recovered 50bbls
Source of Release Sight glass on FWKO	Date and Hour of Occurrence 03-06-2014	Date and Hour of Discovery 03-06-2014 10:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Michelle Mullins	Date and Hour 03-07-2014 07:25am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A sight glass failed on a FWKO at the top connection. Sight glass has been replaced.

Describe Area Affected and Cleanup Action Taken.*

Initially 55bbls of oil released. We were able to recover 50bbls of oil with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor:	
Title: Senior Environmental Coordinator		Approval Date: 3/25/14	Expiration Date: NA
E-mail Address: rgrubbs@concho.com		Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 03-14-2014	Phone: 432-661-6601		

* Attach Additional Sheets If Necessary

2RP-2221