

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP1410129629

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P.	260737	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329	
Facility Name: JRU-124H Tank Battery		Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-38113	


LOCATION OF RELEASE

Unit Letter F	Section 17	Township 23S	Range 31E	Feet from the 2450	North/South Line NORTH	Feet from the 1430	East/West Line WEST	County: Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	-----------------

Latitude N 32.305372 Longitude W 103.802373

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 25 bbls	Volume Recovered: 10 bbls
Source of Release: Water Transfer Pump	Date and Hour of Occurrence: Date 3/27/14 Time unknown	Date and Hour of Discovery: Date 3/27/14 at 1:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Emergency #104 and the BLM	
By Whom? Tony Savoie	Date and Hour: 3/27/14 at 3:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A fitting on the 3" water transfer pump failed due to excessive vibration. The pump was shut down, the fittings were replaced and the pump was repaired.

Describe Area Affected and Cleanup Action Taken.*
The pump was located inside a 0 perm containment around the tanks and pumping equipment, due to the pressure at the release point approximately 17,600 total area of pasture land was impacted by the water being carried east due to high winds. Approximately 10 bbls of fluid was recovered from the containment area. The heavily impacted vegetated area measured approximately 4,000 sq.ft.
The spill area will be cleaned up in accordance with the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: 4/11/14	Expiration Date: NA
E-mail Address: tasavoie@basspet.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: 4/9/14 Phone: 432-556-8730	5/11/14	2PP-2252

* Attach Additional Sheets If Necessary