

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

APR 10 2014

Form C-141
Revised August 8, 2011

Submit 1 copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

Handwritten: 1410539495

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: Cimarex Energy Company <i>162683</i>		Contact: Johnny Titsworth	
Address: 600 N. Marienfield, Suite 600, Midland, TX 79701		Telephone No. (432)250-2059	
Facility Name: Wersell Federal #2		Facility Type: SWD	
Surface Owner: Federal		Mineral Owner: API No: 30-015-24845	

LOCATION OF RELEASE

Unit Letter D	Section 4	Township 22S	Range 27E	Feet from the 660	North/South Line FNL	Feet from the 660	East/West Line FWL	County Eddy
------------------	--------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude: 32.42735 Longitude: -104.2009

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 40	Volume Recovered: 0
Source of Release: 2" pipe	Date & Hour of Occurrence: 3/14/14 10:00	Date & Hour of Discovery: 3/14/14 10:30
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kim Barton	
By Whom? Jennifer Van Curen	Date and Hour: 3/14/14 10:30	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Vibration caused the threads of the 2" pipe to crack at a 45 degree connection. Impacted soil will be assessed and remediated.		
Describe Area Affected and Cleanup Action Taken.* in the pasture: 45'x45', 120'x6', 75'x8'		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>[Signature]</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Johnny Titsworth	Approval Date: 4/15/14	Expiration Date: NA
Title: Environmental Compliance Coordinator	Conditions of Approval:	
E-mail Address: jtitsworth@cimarex.com	Attached <input type="checkbox"/>	
Date: 4/10/14	Phone: (432)-250-2059	

* Attach Additional Sheets, If Necessary

Remediation per OCD Rule &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:**

Handwritten: 5/15/14

Handwritten: 2RP-2260