Form 3160-5	ΙΝΠΤΕΓΣ ΟΤΑΤΕ	OCD Artesia		FORM APPROVED
(Aúgust 2007)	UNITED STATES DEPARTMENT OF THE I BUREAU OF LAND MANA	NTERIOR		OMB NO. 1004-0135 Expires: July 31, 2010
SUNDR	Y NOTICES AND REPO			5. Lease Serial No. NMNM12128
Do not use abandoned v	this form for proposals to vell. Use form 3160-3 (AP	drill or to re-enter an D) for such proposals.		6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA/Agreement, Name and/or	
1. Type of Well ☐ Gas Well ☐ Other			8. Well Name and No. JUNO 27 FEDERAL COM 3	
2. Name of Operator CIMAREX ENERGY COMP	Contact:	DAVID A EYLER		9. API Well No. 30-015-36424-00-S2
3a. Address 600 NORTH MARIENFELD	· · · · · · · · · · · · · · · · · · ·	3b. Phone No. (include area code) Ph: 432-687-3033	)	10. Field and Pool, or Exploratory WILDCAT
MIDLAND, TX 79701 4. Location of Well (Footage, Sec	, T., R., M., or Survey Description	n)		11. County or Parish, and State
Sec 27 T16S R29E SWSW	660FSL 660FWL			EDDY COUNTY, NM
12. CHECK AF	PROPRIATE BOX(ES) TO	O INDICATE NATURE OF 1	NOTICE, RI	LEPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
□ Notice of Intent	C Acidize	Deepen	Produce	tion (Start/Resume) 🔲 Water Shut-
	Alter Casing	□ Fracture Treat	🗖 Reclam	- P,
Subsequent Report	Casing Repair	New Construction	Recomp	
Final Abandonment Notice	Change Plans	Plug and Abandon Plug Back	□ Tempor	rarily Abandon Disposal
following completion of the invol	ved operations. If the operation re	e the Bond No. on file with BLM/BIA esults in a multiple completion or reco	<ol> <li>Required su ompletion in a</li> </ol>	bsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed on
following completion of the invol testing has been completed. Fina determined that the site is ready f 03/16/14: SET 4-1/2"CIBP 03/17.14: TAG CMT. PLUG 2.490'(OK'D BY BLM); MIX	ved operations. If the operation re Abandonment Notices shall be fi or final inspection.) @3,950';CIRC.WELL W/ M @ 3,747'(OK'D BY BLM); X CIRC. TO SURF. 55 SX;	e the Bond No. on file with BLM/BIA ssults in a multiple completion or rece led only after all requirements, includ UD; PUMP 25 SXS.CMT. @ 3, PUMP 25 SXS.CMT. @ 2,720 S.CMT. @ 930'-3'.	A. Required su ompletion in a ling reclamatio ,950';WOC. )'; WOC X T	bsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed on n, have been completed, and the operator has
following completion of the invol testing has been completed. Fina determined that the site is ready f 03/16/14: SET 4-1/2"CIBP 03/17.14: TAG CMT. PLUG 2.490'(OK'D BY BLM); MIX	ved operations. If the operation re Abandonment Notices shall be fi or final inspection.) @3,950';CIRC.WELL W/ M @ @3,747'(OK'D BY BLM); X CIRC. TO SURF. 55 SX OFF WELLHEAD 3' B.G.L.	e the Bond No. on file with BLM/BI/ esults in a multiple completion or rece led only after all requirements, includ UD; PUMP 25 SXS.CMT. @ 3, PUMP 25 SXS.CMT. @ 2,720 S.CMT. @ 930'-3'. ;TOP OFF ALL ANNULI W/ 2	A. Required su ompletion in a ling reclamatio ,950';WOC. '; WOC X T SXS.CMT.;	bsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed on n, have been completed, and the operator has AG CMT. PLUG @
following completion of the invol testing has been completed. Fina determined that the site is ready fr 03/16/14: SET 4-1/2"CIBP 03/17.14: TAG CMT. PLUG 2,490'(OK'D BY BLM); MIX 03/18/14: DIG OUT X CUT	ved operations. If the operation re Abandonment Notices shall be fi or final inspection.) @3,950';CIRC.WELL W/ M @ 3,747'(OK'D BY BLM); X CIRC. TO SURF. 55 SX: OFF WELLHEAD 3' B.G.L. TO CSGS. X INSTALL DRY	e the Bond No. on file with BLM/BI/ esults in a multiple completion or rect led only after all requirements, includ UD; PUMP 25 SXS.CMT. @ 3, PUMP 25 SXS.CMT. @ 2,720 S.CMT. @ 930'-3'. ;TOP OFF ALL ANNULI W/ 2 Y HOLE MARKER.	A. Required su ompletion in a ling reclamatio ,950';WOC. '; WOC X T SXS.CMT.;	bsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed on n, have been completed, and the operator has AG CMT. PLUG @
following completion of the invol testing has been completed. Final determined that the site is ready f 03/16/14: SET 4-1/2"CIBP 03/17.14: TAG CMT. PLUC 2,490'(OK'D BY BLM); MIX 03/18/14: DIG OUT X CUT WELD ON STEEL PLATE WELL PLUGGED AND AB	ved operations. If the operation re Abandonment Notices shall be fi or final inspection.) @3,950';CIRC.WELL W/ M & @3,747'(OK'D BY BLM); X CIRC. TO SURF. 55 SX: CFF WELLHEAD 3' B.G.L. TO CSGS. X INSTALL DRY ANDONED 03/18/14.	e the Bond No. on file with BLM/BI/ esults in a multiple completion or rect led only after all requirements, includ UD; PUMP 25 SXS.CMT. @ 3, PUMP 25 SXS.CMT. @ 2,720 S.CMT. @ 930'-3'. ;TOP OFF ALL ANNULI W/ 2 Y HOLE MARKER.	A. Required su ompletion in a ding reclamatio ,950';WOC. '; WOC X T SXS.CMT.; Accopte	al as to plugging of the well bore.
following completion of the invol testing has been completed. Final determined that the site is ready for 03/16/14: SET 4-1/2"CIBP 03/17.14: TAG CMT. PLUC 2,490'(OK'D BY BLM); MIX 03/18/14: DIG OUT X CUT WELD ON STEEL PLATE WELL PLUGGED AND AB	ved operations. If the operation re Abandonment Notices shall be fi or final inspection.) @3,950';CIRC.WELL W/ M & @3,747'(OK'D BY BLM); X CIRC. TO SURF. 55 SX: CFF WELLHEAD 3' B.G.L. TO CSGS. X INSTALL DRY ANDONED 03/18/14.	e the Bond No. on file with BLM/BIA esults in a multiple completion or recei- led only after all requirements, includ UD; PUMP 25 SXS.CMT.@ 3, PUMP 25 SXS.CMT.@ 2,720 S.CMT.@ 930'-3'. ;TOP OFF ALL ANNULI W/ 2 HOLE MARKER.	A. Required su ompletion in a ding reclamatio ,950';WOC. '; WOC X T SXS.CMT.; Accopte	bsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed on n, have been completed, and the operator has
following completion of the invol testing has been completed. Final determined that the site is ready f 03/16/14: SET 4-1/2"CIBP 03/17.14: TAG CMT. PLUC 2,490'(OK'D BY BLM); MIX 03/18/14: DIG OUT X CUT WELD ON STEEL PLATE WELL PLUGGED AND AB	ved operations. If the operation re Abandonment Notices shall be fi or final inspection.) @3,950';CIRC.WELL W/ M & @3,747'(OK'D BY BLM); X CIRC. TO SURF. 55 SX: CFF WELLHEAD 3' B.G.L. TO CSGS. X INSTALL DRY ANDONED 03/18/14.	e the Bond No. on file with BLM/BIA esults in a multiple completion or reco led only after all requirements, includ UD; PUMP 25 SXS.CMT. @ 3, PUMP 25 SXS.CMT. @ 2,720 S.CMT. @ 930'-3'. ;TOP OFF ALL ANNULI W/ 2 Y HOLE MARKER. RECEIVED APR 1 5 2014	A. Required su ompletion in a ling reclamatio 950';WOC. '; WOC X T SXS.CMT.; Accord Surface	bequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed on n, have been completed, and the operator has AG CMT. PLUG @
following completion of the invol testing has been completed. Final determined that the site is ready for 03/16/14: SET 4-1/2"CIBP 03/17.14: TAG CMT. PLUG 2,490'(OK'D BY BLM); MIX 03/18/14: DIG OUT X CUT WELD ON STEEL PLATE WELL PLUGGED AND AB RECLAMATION DUE	ved operations. If the operation re Abandonment Notices shall be fi or final inspection.) @3,950';CIRC.WELL W/ M § @ 3,747'(OK'D BY BLM); X CIRC. TO SURF. 55 SX: OFF WELLHEAD 3' B.G.L. TO CSGS. X INSTALL DRY ANDONED 03/18/14.	e the Bond No. on file with BLM/BIA esults in a multiple completion or reci- led only after all requirements, includ UD; PUMP 25 SXS.CMT.@ 3 PUMP 25 SXS.CMT.@ 2,720 S.CMT.@ 930'-3' ; TOP OFF ALL ANNULI W/ 2 HOLE MARKER. RECEIVED APR 1 5 2014	A. Required su ompletion in a ling reclamatio 950';WOC V; WOC X T SXS.CMT.; Accopte Viabilit Surface	bequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed on in, have been completed, and the operator has AG CMT. PLUG @ ad as to plugging of the well bore, y under bord is completed. I restoration is completed.
following completion of the invol testing has been completed. Final determined that the site is ready for 03/16/14: SET 4-1/2"CIBP 03/17.14: TAG CMT. PLUC 2,490'(OK'D BY BLM); MIX 03/18/14: DIG OUT X CUT WELD ON STEEL PLATE WELL PLUGGED AND AB	ved operations. If the operation re Abandonment Notices shall be fi or final inspection.) @3,950';CIRC.WELL W/ M & @3,747'(OK'D BY BLM); X CIRC. TO SURF. 55 SX' OFF WELLHEAD 3' B.G.L. TO CSGS. X INSTALL DRY ANDONED 03/18/14. g is true and correct. Electronic Submission # For CIMAREX EN	e the Bond No. on file with BLM/BIA esults in a multiple completion or rece led only after all requirements, includ UD; PUMP 25 SXS.CMT.@ 3, PUMP 25 SXS.CMT.@ 2,720 S.CMT.@ 930'-3'. ;TOP OFF ALL ANNULI W/ 2 HOLE MARKER.	A. Required su ompletion in a ding reclamatio ,950';WOC. '; WOC X T SXS.CMT.; Accepto Surface Surface	bsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed on in, have been completed, and the operator has AG CMT. PLUG @ ad as to plugging of the well bore, y under borth is completed. restoration is completed.
following completion of the invol testing has been completed. Fina determined that the site is ready for 03/16/14: SET 4-1/2"CIBP 03/17.14: TAG CMT. PLUC 2,490'(OK'D BY BLM); MIX 03/18/14: DIG OUT X CUT WELD ON STEEL PLATE WELL PLUGGED AND AB RECLAMATION DUE 9.14.14 14. I hereby certify that the foregoin	ved operations. If the operation re Abandonment Notices shall be fi or final inspection.) @3,950';CIRC.WELL W/ M & @ 3,747'(OK'D BY BLM); X CIRC. TO SURF. 55 SX: OFF WELLHEAD 3' B.G.L. TO CSGS. X INSTALL DRY ANDONED 03/18/14. g is true and correct. Electronic Submission # For CIMAREX EN Committed to AFMSS for pr	e the Bond No. on file with BLM/BIA sults in a multiple completion or rece led only after all requirements, includ UD; PUMP 25 SXS.CMT.@ 2,720 S.CMT.@ 930'-3' ;TOP OFF ALL ANNULI W/ 2 HOLE MARKER.	A. Required su ompletion in a ding reclamatio ,950';WOC. ';WOC X T SXS.CMT.; Accepte Surface Surface dil Informatio to the Carlsb 03/28/2014 (1	bsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed on in, have been completed, and the operator has AG CMT. PLUG @ ad as to plugging of the well bore, y under borth is completed. restoration is completed.
following completion of the invol testing has been completed. Fina determined that the site is ready for 03/16/14: SET 4-1/2"CIBP 03/17.14: TAG CMT. PLUC 2,490'(OK'D BY BLM); MIX 03/18/14: DIG OUT X CUT WELD ON STEEL PLATE WELL PLUGGED AND AB RECLAMATION DUE 9-14-14	ved operations. If the operation re Abandonment Notices shall be fi or final inspection.) @3,950';CIRC.WELL W/ M & @3,747'(OK'D BY BLM); X CIRC. TO SURF. 55 SX' OFF WELLHEAD 3' B.G.L. TO CSGS. X INSTALL DRY ANDONED 03/18/14. g is true and correct. Electronic Submission # For CIMAREX EN	e the Bond No. on file with BLM/BIA esults in a multiple completion or rece led only after all requirements, includ UD; PUMP 25 SXS.CMT.@ 3, PUMP 25 SXS.CMT.@ 2,720 S.CMT.@ 930'-3'. ;TOP OFF ALL ANNULI W/ 2 HOLE MARKER.	A. Required su ompletion in a ding reclamatio ,950';WOC. ';WOC X T SXS.CMT.; Accepte Surface Surface dil Informatio to the Carlsb 03/28/2014 (1	bsequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed on in, have been completed, and the operator has AG CMT. PLUG @ ad as to plugging of the well bore, y under bord is completed. restoration is completed.
following completion of the invol testing has been completed. Final determined that the site is ready fr 03/16/14: SET 4-1/2"CIBP 03/17.14: TAG CMT. PLUC 2,490'(OK'D BY BLM); MIX 03/18/14: DIG OUT X CUT WELD ON STEEL PLATE WELL PLUGGED AND AB RECLAMATION DUE	ved operations. If the operation re Abandonment Notices shall be fi or final inspection.) (23,950';CIRC.WELL W/ M (3), 3,747'(OK'D BY BLM); X CIRC. TO SURF. 55 SX: OFF WELLHEAD 3' B.G.L. TO CSGS. X INSTALL DRY ANDONED 03/18/14. (3) (3) (3) (3) (4) (5) (5) (5) (5) (5) (5) (5) (5) (5) (5	e the Bond No. on file with BLM/BIA sults in a multiple completion or reco led only after all requirements, includ UD; PUMP 25 SXS.CMT.@ 2,720 S.CMT.@ 930'-3' ;TOP OFF ALL ANNULI W/ 2 HOLE MARKER.	A. Required su ompletion in a ling reclamatio ,950';WOC. ';WOC X T SXS.CMT.; Accepte Surface Surface oto the Carist 03/28/2014 (1	bequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed on in, have been completed, and the operator has AG CMT. PLUG @ ad as to plugging of the well bore, y under bord is completed. I restoration is completed. MD restoration is completed.
following completion of the invol testing has been completed. Final determined that the site is ready fr 03/16/14: SET 4-1/2"CIBP 03/17.14: TAG CMT. PLUC 2,490'(OK'D BY BLM); MIX 03/18/14: DIG OUT X CUT WELD ON STEEL PLATE WELL PLUGGED AND AB RECLAMATION DUE	ved operations. If the operation re Abandonment Notices shall be fi or final inspection.) (23,950';CIRC.WELL W/ M (3), 3,747'(OK'D BY BLM); X CIRC. TO SURF. 55 SX: OFF WELLHEAD 3' B.G.L. TO CSGS. X INSTALL DRY ANDONED 03/18/14. (3) (3) (3) (3) (4) (5) (5) (5) (5) (5) (5) (5) (5) (5) (5	e the Bond No. on file with BLM/BI/ esults in a multiple completion or reci- led only after all requirements, includ UD; PUMP 25 SXS.CMT. @ 2,720 S.CMT. @ 930'-3' ;TOP OFF ALL ANNULI W/ 2 HOLE MARKER.	A. Required su ompletion in a ding reclamatio ,950'; WOC. T SXS.CMT.; Accepte Liabilit Surface 03/28/2014 (1 C 2014 OFFICE U	bequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed on in, have been completed, and the operator has AG CMT. PLUG @ bd as to plugging of the well bore, y under bord is completed. I restoration is completed. MD restoration is completed.
following completion of the invol testing has been completed. Final determined that the site is ready for 03/16/14: SET 4-1/2"CIBP 03/17.14: TAG CMT. PLUC 2,490'(OK'D BY BLM); MIX 03/18/14: DIG OUT X CUT WELD ON STEEL PLATE WELL PLUGGED AND AB RECLAMATION DUE. 9-14-14 14. I hereby certify that the foregoin Name (Printed/Typed) DAVID Signature (Electron Approved By ACCEP	ved operations. If the operation re Abandonment Notices shall be fi or final inspection.) (23,950';CIRC.WELL W/ M (3) (3,747'(OK'D BY BLM); X CIRC. TO SURF. 55 SX: OFF WELLHEAD 3' B.G.L. TO CSGS. X INSTALL DRY ANDONED 03/18/14. (3) (3) (3) (3) (3) (3) (3) (3) (3) (3)	e the Bond No. on file with BLM/BI/ esults in a multiple completion or reci- led only after all requirements, includ UD; PUMP 25 SXS.CMT.@ 3, PUMP 25 SXS.CMT.@ 2,720 S.CMT.@ 930'-3' ; TOP OFF ALL ANNULI W/ 2 HOLE MARKER.	A. Required su ompletion in a ding reclamatio ,950'; WOC. '; WOC X T SXS.CMT.; Accorpto ); abilit Surface 03/28/2014 (1 C CO14 OFFICE U AMOS	bequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed on in, have been completed, and the operator has AG CMT. PLUG @ ad as to plugging of the well bore, y under bond is rescious with restoration is completed.
following completion of the invol testing has been completed. Final determined that the site is ready fi 03/16/14: SET 4-1/2"CIBP 03/17.14: TAG CMT. PLUC 2,490'(OK'D BY BLM), MIX 03/18/14: DIG OUT X CUT WELD ON STEEL PLATE WELL PLUGGED AND AB RECLAMATION DUE	ved operations. If the operation re Abandonment Notices shall be fi or final inspection.) @3,950';CIRC.WELL W/ M & @3,747'(OK'D BY BLM); X CIRC. TO SURF. 55 SX: OFF WELLHEAD 3' B.G.L. TO CSGS. X INSTALL DRY ANDONED 03/18/14. g is true and correct. Electronic Submission f For CIMAREX EN Committed to AFMSS for pr A EYLER ic Submission) THIS SPACE F( TED	e the Bond No. on file with BLM/BI/ esults in a multiple completion or reci- led only after all requirements, includ UD; PUMP 25 SXS.CMT. @ 2,720 S.CMT. @ 930'-3' ;TOP OFF ALL ANNULI W/ 2 HOLE MARKER.	A. Required su ompletion in a ding reclamatio ,950';WOC. Y; WOC X T SXS.CMT.; Accepto Surfacs Surfacs 03/28/2014 (1 C 2014 OFFICE U AMOS SOR EPS	bequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed on in, have been completed, and the operator has AG CMT. PLUG @ ad as to plugging of the well bors, y under bond to rescious to the restoration is completed.
following completion of the invol testing has been completed. Final determined that the site is ready for 03/16/14: SET 4-1/2"CIBP 03/17.14: TAG CMT. PLUC 2,490'(OK'D BY BLM); MIX 03/18/14: DIG OUT X CUT WELD ON STEEL PLATE WELL PLUGGED AND AB RECLAMATION DUE 9-14-14 14. I hereby certify that the foregoin Name (Printed/Typed) DAVID Signature (Electron Approved By ACCEP Conditions of approval, if any, are atta certify that the applicant holds legal or which would entitle the applicant to co	ved operations. If the operation re Abandonment Notices shall be fi or final inspection.) @3,950';CIRC.WELL W/ M & @3,747'(OK'D BY BLM); X CIRC. TO SURF. 55 SX: OFF WELLHEAD 3' B.G.L. TO CSGS. X INSTALL DRY ANDONED 03/18/14. g is true and correct. Electronic Submission # For CIMAREX EN Committed to AFMSS for pr A EYLER ic Submission) THIS SPACE F( TED ched. Approval of this notice doe equitable title to those rights in th nduct operations thereon.	e the Bond No. on file with BLM/BI/ esults in a multiple completion or reci- led only after all requirements, includ UD; PUMP 25 SXS.CMT. @ 2,720 S.CMT. @ 930'-3' ;TOP OFF ALL ANNULI W/ 2 HOLE MARKER.	A. Required su ompletion in a ding reclamatio ,950';WOC. ';WOC X T SXS.CMT.; Accepte Surfacs Surfacs Office U AMOS SOR EPS d	bequent reports shall be filed within 30 days new interval, a Form 3160-4 shall be filed on in, have been completed, and the operator has AG CMT. PLUG @ ad as to plugging of the well bore, y under bord is completed. I restoration is completed. MD restoration is completed.