

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

WHP 1413238288

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: CIMAREX ENERGY 162683	Contact: James Tinney
Address : 600 N Marienfeld Ste 600, Midland TX 79701	Telephone No. (575) 706-0095
Facility Name: Crow Flats 16 state 2H	Facility Type: Production Battery

Surface Owner	Mineral Owner	API No. 30-015-35556
---------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter M	Section 16	Township 016-S	Range 028-E	Feet from the 660	North/South Line south	Feet from the 330	East/West Line west	County ; Eddy
------------------	---------------	-------------------	----------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude: 32.917130 Longitude: -104.188290

NATURE OF RELEASE

Oil 2PW

Type of Release: oil/produce water	Volume of Release: 15 oil/5 pw	Volume Recovered: 12 bbls total
Source of Release: hole in heater fire tube	Date and Hour of Occurrence: 5/4/2014 @ 0900 hrs	Date and Hour of Discovery: 5/4/2014 @ 0900 hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, 5/5/14 @ 0710 hrs, no answer left message	
By Whom? James Tinney	Date and Hour: 5/5/14 @ 0710 hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED

MAY 07 2014

NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* hole in fire tube on heater, picked up standing oil and produce water. Release was in an unlined berm.

Describe Area Affected and Cleanup Action Taken.*

Area affected 36' x 30' contained inside dirt berm (unlined). Called vac truck picked up standing oil and emptied heater. Work plan: repair equipment, pick up contaminated soil.

Delimitation Samples Required

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: James Tinney

Printed Name: James Tinney

Title: Production Foreman

E-mail Address: jtinney@cimarex.com

Date: 05/05/2014

Phone: (575) 706-0095

Attach Additional Sheets If Necessary

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

Approval Date: 5/12/14

Expiration Date: NA

Conditions of Approval:
Remediation per OCD Rule &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:**
6/12/14

Attached ☐

2RP-2294