

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

MAY 13 2014

NMOCD ARTESIA

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP1413432969

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company - EOG Resources, Inc.	7377	Contact - Ryan Kainer
Address - 5509 Champions Drive, Midland, TX 79706		Telephone No. (432) 686-3662
Facility Name - Elk Wallow 11 #3		Facility Type - Oil Well

Surface Owner - New Mexico	Mineral Owner - New Mexico	API No. 30-015-37590
----------------------------	----------------------------	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 11	Township T25S	Range R29E	Feet from the 80	North/South Line N	Feet from the 1650	East/West Line East	County Eddy
------------------	---------------	------------------	---------------	---------------------	-----------------------	-----------------------	------------------------	----------------

Latitude 32.1516 Longitude -103.9519

NATURE OF RELEASE

Type of Release - Oil	Volume of Release - 45 bbls	Volume Recovered - 20 bbls
Source of Release - Flare leaked oil on location	Date and Hour of Occurrence: 5/7/2014, 6:00 PM	Date and Hour of Discovery: 5/7/2014
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffery Leking (NMOCD)	
By Whom? Ryan Kainer	Date and Hour 5/10/2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NA

Describe Cause of Problem and Remedial Action Taken.*

Approximately 45 bbls of oil leaked from the flare onto location with approx. 20 bbls recovered. No fluids migrated off the location.

B.O. back pressure valve on heater was replaced and remediation of the spill is underway.

Describe Area Affected and Cleanup Action Taken.*

The spill area will be sampled and analyzed for Total Petroleum Hydrocarbons. The impacted area will be excavated, stockpiled on poly-plastic, and transported to an approve disposal facility. Clean material will be backfilled within the excavated area to normal grade.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Ryan Kainer

Title: Sr. Safety & Environmental Rep.

E-mail Address: ryan_kainer@eogresources.com

Date: 5/12/2014

Phone: 432-686-3662

Approved by Environmental Specialist:

Approval Date: 5/14/14

Expiration Date: NA

Conditions of Approval:

Attached ☐

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:
6/14/14

2RP-2301

* Attach Additional Sheets If Necessary