<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141 Revised August 8, 2011

Release Notification and Corrective Action

						OPERATOR Initial F					\boxtimes	Final Report
Name of Company: BOPCO, L.P.						Contact: To						
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220						Telephone No. 575-887-7329						
Facility Name: Poker Lake Unit #211						Facility Type: Exploration and Production						
Surface Owner: Federal Mineral Owner:						Federal API No. 30-015-33858						
LOCATION OF RELEASE												
									East/West Line County			
J	18	24S	30E	1980	So	outh	1980	E	East Eddy			
	<u> </u>	1		Latitude 32	21579	792 Longitude 103.918552						
NATURE OF RELEASE												
Type of Rele	ase: Produc	ed Water and		Volume of Release 10 bbls crude oil and 15 bbls produced water Volume Recovered: 5 bbls total fluid								
Source of Re	lease: Pump	ping well stuff		Date and Hour of Occurrence Date and Hour of Discovery 7/15/12 7/15/12 Time Unknown Approximately 12:45 p.m.						7/15/12		
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? NMOCD Emergency #104 and Jim Amos "BLM"						
By Whom? Tony Savoie						Date and Hour: 7/16/12 at 9:05 a.m.						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
☐ Yes ☐ No						RECEIVED						
If a Watercou	ırse was Im	pacted, Descr	ibe Fully.*	•		1 1	-		1			İ
							MAY 09 2	014				
Describe Cause of Problem and Remedial Action Taken.* The well was shut in and the stuffing box packing was replaced. NMOCD ARTESIA												
Describe Area Affected and Cleanup Action Taken.* Approximately 8925 sq. ft. of caliche well pad and approximately 840 sq. ft of pasture was affected by the release, a vacuum truck was used to pick up the free standing fluid and a backhoe was used to scrape up the heavily saturated soil on the well pad, the material was stockpiled on-site. The remediation will follow the NMOCD and BLM spill Guidelines.												
Approximately 1,120 cu. yds of impacted soil was excavated from an area measuring approximately 10' to 40' in width, 220' in length, and 1' to 2' in depth. Impacted soil was hauled to an NMOCD-approved disposal facility. Confirmation soil samples were collected on approximate 50' intervals and submitted for laboratory analysis. Please reference the attached Remediation Summary and Site Closure Request for detail of Remediation Activities.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
						OIL CONSERVATION DIVISION						
Signature:	1 Ou	Zu		1/								
Printed Name: Tony Savoie						Approved by Environmental Specialist:						
Title: Waste Management and Remediation Specialist						Approval Date: 5/15/14 Expiration Date: WA						
E-mail Address: tasavoie@basspet.com						Conditions of Approval:						
Date: 5	19/10	Į.		Final								
Attach Addi		<u> </u>		432-556-8730					_	2RG	> -17	32