

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company EOG Resources, Inc.	Contact Renee Jarratt
Address P.O. Box 2267, Midland, TX 79702	Telephone No. (432) 686-3684
Facility Name West Brushy 27 Federal #1	Facility Type Tank Battery

Surface Owner: Federal	Mineral Owner	Lease No.
-------------------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section 11	Township 25S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------

Latitude N 32.853001° Longitude W 103.959150°

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 80 bbls	Volume Recovered 0 bbls
Source of Release: Cut Flowline	Date and Hour of Occurrence 11/30/2010 7:00 am	Date and Hour of Discovery 11/30/2010 8:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Josh Russo	Date and Hour 3/15/10 4:59 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

RECEIVED

MAR 05 2014

NMOCD ARTESIA



Describe Cause of Problem and Remedial Action Taken.*

COG contracted Production Specialty to remove their flowline, Production Specialty cut into EOG's line by mistake, causing the release. Production Specialty has accepted all financial responsibility for the cleanup.

Describe Area Affected and Cleanup Action Taken.*

Tetra Tech inspected site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal and a clay cap was installed in necessary areas. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez	Approved by District Supervisor: 	
Title: Project Manager	Approval Date: 5/16/14	Expiration Date: NA
E-mail Address: Ike.Tavarez@TetraTech.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 1-30-14	Phone: (432) 682-4559	

* Attach Additional Sheets If Necessary

2RP-496