


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: Cimarex Energy Company <b>215099</b>	Contact: Johnny Titsworth
Address: 600 N. Marienfield, Suite 600, Midland, TX 79701	Telephone No. (432)250-2059
Facility Name: Sandy Unit 21H	Facility Type: Drilling Rig

Surface Owner: Federal	Mineral Owner:	API No: 30-015-41791
------------------------	----------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	23	23S	30E	225	FSL	250	FEL	Eddy

Latitude: 32.283839 Longitude: -103.843781

**NATURE OF RELEASE**

Type of Release: brine mud	Volume of Release: 80 BBLs	Volume Recovered: 80 BBLs
Source of Release:	Date & Hour of Occurrence: 5/28/14 12:00 pm	Date & Hour of Discovery: 5/28/14 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD / Jennifer Van Curen - BLM	
By Whom? Johnny Titsworth	Date and Hour: 5/28/14 9:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted. Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The suction hose parted on mud pump #1 causing approximately 80 bbls of cut brine mud to spill on the ground around the mud pumps and pit. Crews were cleaning up the spill around the pump getting everything into the ditches that they can so that it can be sucked up.

Describe Area Affected and Cleanup Action Taken.\*

The spill was contained on location with most of it caught in the secondary containment ditches around the pump. The area will be addressed when the rig moves off location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Johnny Titsworth		Approved by Environmental Specialist:	
Title: Environmental Compliance Coordinator		Approval Date: 5/30/14	Expiration Date: NA
E-mail Address: jtitsworth@cimarex.com		Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION</b>	
Date: 5/28/14	Phone: (432)-250-2059	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

**PROPOSAL NO LATER THAN:**  
6/30/14

2PP-2322