



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/District III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3 June 2014 Operator Burlington API #30-0 45 07835

Property Name MANGLIN Well No. 1 Location: Unit Section 27 Township 29 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 34 Intermediate N/A Casing 34 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min			34		
10 min			34		
15 min			34		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

OIL CONS. DIV DIST. 3

JUN 3 2014

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT.

By ROBERT CHAVEZ

Witness John Dufan

(Position)

E-mail address