

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company BOPCO	Contact: Nancy Fitzwater
Address: 522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No.
Facility Name: Poker Lake Unit Well #241 2RP-1173	Facility Type

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-34308
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter O	Section 30	Township 24S	Range 30E	Feet from the 840	North/South Line South	Feet from the 2030	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	-------------

Latitude 32.86647 Longitude 103.8571

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release 9 bbls	Volume Recovered 0
Source of Release 2 7/8" flow line	Date and Hour of Occurrence 5/23/12 Time unknown	Date and Hour of Discovery: 05/23/12 3:46 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour 01-22-13 2:20 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*
The flow line developed a leak due to external corrosion. One joint of pipe was replaced.

RECEIVED

MAR 18 2014

NMOCD ARTESIA

Describe Area Affected and Cleanup Action Taken.*
Approximately 420 sq. ft. of pasture land. All of the released fluid soaked into the ground. The spill location was right of the south edge of the well pad, it appeared to be near a reclaimed drill pit location. The remediation complies with the NMOCD and BLM requirements for spills.
BOPCO respectfully request closure of this incident.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Tony Savoie*

Printed Name: Tony Savoie

Title: Waste Mgmt. & Remediation Specialist

E-mail Address: TASavoie@BassPet.com

Date: 3/12/14

Phone: 432-556-8730

Approved by Environmental Specialist: *Hunter*

Approval Date: 5/15/14

Expiration Date: NA

Conditions of Approval:

Attached ☐

Final

* Attach Additional Sheets If Necessary

2RP-1173