

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAY 29 2014

NMOCD ARTESIA

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC

Form C-141  
Revised October 10, 2003

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	Contact: Brian Wall	
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739	
Facility Name: Barclay Federal 20	Facility Type: Oil producer	
Surface Owner: Federal	Mineral Owner:	API No.: 30-015-30821

LOCATION OF RELEASE

Unit Letter P	Section 01	Township 23S	Range 31E	Feet from the 660	North/South Line South	Feet from the 660	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude: 32.3279024953782 Longitude: -103.725139949875

NATURE OF RELEASE



Type of Release: Produced Water / Oil	Volume of Release: 2 bbls/ 6bbls	Volume Recovered: 0 / 5bbls
Source of Release: Pipeline steel	Date and Hour of Occurrence: 05/24/14	Date and Hour of Discovery: 05/24/14 11:49am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jennifer Van Curren- BLM · Mike Bratcher-NMOCD	
By Whom? Brian Wall	Date and Hour 05/27/2014 0646	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: upon checking wells I notice a leak on a flowline in the pasture. I shut down the well and called for a vac truck and a roustabout crew

Describe Area Affected and Cleanup Action Taken.\*: Delineate spill site, and remove contaminated as suggested by BLM and OCD. Haul to approved disposal site and return clean soils to fill void at site. Return to natural terrain and close site via approval of BLM and OCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor: 	
Title: Construction Foreman II	Approval Date: 6/12/14	Expiration Date: NA
E-mail Address: bwall@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 05/29/2014	Phone: 806-367-0645	

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines, &  
like approval by BLM. SUBMIT REMEDIATION  
PROPOSAL NO LATER THAN:  
7/12/14

2RP-2337