


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

Handwritten: Haul 1412237021

OPERATOR Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Chase Settle
Address 104 S. 4 TH Street	Telephone No. 575-748-4171	
Facility Name Rudolph ATX State Com. #3-H	API Number 30-015-37997	Facility Type Battery
Surface Owner State	Mineral Owner State	Lease No. V-4567

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	16	19S	31E	330'	South	660'	West	Eddy

Latitude 32.65389 Longitude -103.88026

NATURE OF RELEASE

Type of Release Crude Oil and Produced Water	Volume of Release 5 B/O; 147 B/PW	Volume Recovered 5 B/O; 147 B/PW
Source of Release High wind caused the water leg to break.	Date and Hour of Occurrence 04/4/2014; AM	Date and Hour of Discovery 04/4/2014; PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, Randy Dade	
By Whom? Chase Settle	Date and Hour 04/04/2014 6:34 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No.	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* High winds caused the water leg to break, valves were closed to the tank, and vacuum truck was called to retrieve standing fluid.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 300' X 10' was affected within the lined/bermed battery. Vacuum truck was called to remove standing oil and roustabout crew called to remove impacted soils. Vacuum truck removed standing fluid (78 B/PW) and the rest of the released fluid (5 B/O, 69 B/PW) was entrapped in the sand and gravel within the lined berm and excavated. Excavated soils will be hauled to a NMOCD approved facility. All released fluid was retrieved by the vacuum truck and excavation of sand and gravel, a Final Report, C-141 is submitted to the OCD requesting closure. Depth to Ground Water: >100' (approximately 150', Section 16, T19S-R31E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 0.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Chase Settle	Approved by District Supervisor:	
Title: NM Environmental Regulatory Agent	Approval Date: <u>5/2/14</u>	Expiration Date: <u>NA</u>
E-mail Address: csettle@yatespetroleum.com	Conditions of Approval: <u>Final</u>	Attached <input type="checkbox"/>
Date: Wednesday, April 16, 2014 Phone: 575-748-4171	2RP-	

* Attach Additional Sheets If Necessary

Handwritten: 2RP-2283