

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 21 2014

Form C-141
Revised October 10, 2003

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NAB1431242205

NAME OF COMPANY COG OPERATING LLC <i>229/37</i>		OPERATOR <input checked="" type="checkbox"/> Initial Report <input checked="" type="checkbox"/> Final Report	
Address 600 West Illinois Avenue, Midland, TX 79701		Contact Robert McNeill	
Facility Name Bragg 10 Fee #1H		Telephone No. 432-230-0077	
		Facility Type Battery	

Surface Owner : Fee	Mineral Owner : Fee	Lease No. (API#) 30-015-41462
----------------------------	----------------------------	--------------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	10	19S	26E	150	South	105	West	Eddy

Latitude Longitude

NATURE OF RELEASE

Type of Release Produced water and Condensate	Volume of Release 20 bbls Oil; 70 bbls PW	Volume Recovered 20 bbls Oil; 70 bbls PW
Source of Release 4" T at the inlet of the separator	Date and Hour of Occurrence 07-13-2014 3:00 pm	Date and Hour of Discovery 07-13-2014 3:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD/Jeffery Robertson - BLM	
By Whom? Amanda Trujillo	Date and Hour 07-14-2014 04:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

4" T at inlet of the separator failed. Release occurred inside lined facility. All free standing fluids picked up and disposed of at an NMOCD approved facility. Replaced bad fitting with new plastic coated fitting.

Describe Area Affected and Cleanup Action Taken.*

All free fluids have been recovered. A vacuum truck and steam cleaner cleaned containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by District Supervisor: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: 7/31/14	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: 07-21-2014 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

2RP-2410