

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NA 14224538164

OPERATOR Initial Report Final Report

Name of Company: ConocoPhillips <i>217817</i>	Contact: José Zepeda
Address: 1410 N. West County Road	Telephone No. 575-391-3165
Facility Name: James A Water Station	Facility Type: Water Station

Surface Owner: NMOCD	Mineral Owner: N/A	API No. 300152671	30-015-26761
-----------------------------	---------------------------	--------------------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	02	22S	30E	1250	South	1150	East	Eddy

Latitude **32.41729** Longitude **103.84731**

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 35.4 BBLS	Volume Recovered: 0 BBLS
Source of Release: Injection pump	Date and Hour of Occurrence: 06/05/2014 5:25 am	Date and Hour of Discovery: 06/04/2014 08:45 hrs.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking	
By Whom? Jay Garcia	Date and Hour: 6/5/2014 11:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
COPC employee arrived on location and discovered a release at the James A Water Station due to plunger failure on the injection pump. Injection pump was isolated and release stopped. Employee notified supervisor and MSO. LOTO was performed.

Describe Area Affected and Cleanup Action Taken.*
Affected area was 172ft X 37ft all on caliche pad and will be remediated according to NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jay Garcia</i>	OIL CONSERVATION DIVISION	
Printed Name: Jay Garcia	Signed By <i>Mike Brannon</i> Approved by Environmental Specialist:	
Title: LEAD HSE	Approval Date: <i>8/12/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: jay.c.garcia@conocophillips.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION Attached <input type="checkbox"/>	
Date: 6/5/2014 Phone: 575-391-3180	PROPOSAL NO LATER THAN: <i>9/12/14</i>	

* Attach Additional Sheets If Necessary

2 RP-2436