


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

**Release Notification and Corrective Action**

*NAB1422627735*

**OPERATOR**

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	25575	Contact Robert Asher
Address 104 S. 4 <sup>th</sup> Street		Telephone No. 575-748-4217
Facility Name Glow Worm ALX Federal #13		Facility Type Battery

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-35315
--------------------------	--------------------------	-------------------------

**LOCATION OF RELEASE**

Unit Letter B	Section 4	Township 23S	Range 31E	Feet from the 330	North/South Line North	Feet from the 2160	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.33971 Longitude 103.78125

**NATURE OF RELEASE**

Type of Release Crude Oil & Produced Water	Volume of Release 1 B/O & 4 B/PW	Volume Recovered 1 B/O & 0 B/PW
Source of Release 4 inch poly line	Date and Hour of Occurrence 8/6/2014; AM	Date and Hour of Discovery 8/6/2014; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

There was a leak in the poly line, causing the release. The well was shut off and vacuum truck(s) and roustabout crew called.

Describe Area Affected and Cleanup Action Taken.\*

An approximate area of overspray that covered an approximate area of 30 X 60'. The line was repaired and the oversprayed area will be brush-hog mowed and Micro Blazed. **Depth to Ground Water: >100' (approximately 100', Section 4, T23S-R31E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 0. Based on the small amounts released and the remedial actions taken, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCN rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCN marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCN acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Asher		Approved by Environmental Specialist: <i>Mike Brown</i>	
Title: NM Environmental Regulatory Supervisor		Approval Date: <i>8/14/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: boba@yatespetroleum.com		Conditions of Approval: <i>Final</i>	
Date: August 13, 2014 Phone: 575-748-4217		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

*2RP-2437*