


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

*0AB1423248613*

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name:	Blue Thunder 4 Federal #1	Facility Type:	Battery
Surface Owner: Federal	Mineral Owner: Federal	Lease No. (API#)	30-015-34125

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	4	19S	31E	810	South	660	West	30-015-34125

Latitude N32° 41.070 Longitude W103° 52.844

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release Oil: 8 bbls ; PW: 33 bbls	Volume Recovered Oil: 0 bbls ; PW: 0 bbls
Source of Release Hole in tank bottom	Date and Hour of Occurrence 8/4/2014 9:30 am	Date and Hour of Discovery 8/4/2014 10:40 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD; James Amos - BLM	
By Whom? Amanda Trujillo	Date and Hour 8/4/2014 6:09 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A hole in the tank bottom caused a release. The facility was unlined but crews were able to excavate impacted material and dispose of it at an approved NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.\*

The impacted area can be found within the bermed area around the tanks. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by District Supervisor: <i>Mike Bratcher</i>	Signed By: <i>Mike Bratcher</i>
Title: Senior Environmental Coordinator	Approval Date: <i>8/20/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>9/20/14</i>	Attached <input type="checkbox"/>
Date August 15, 2014 Phone: 575-746-2010		

\* Attach Additional Sheets If Necessary

*2 RP-2AB*