Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia


FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

5. Lease Serial No. NMNM112268

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

abandoned well. Use i	-orm 3160-3 (A	PD) for suc	n proposais	•				
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. Preacher 19 Federal 3H			
Name of Operator Devon Energy Production Company, L.P.					9. API Well No. 30-015-41887			
3a. Address 333 W. Sheridan Avenue Oklahoma City, Oklahoma 73102	3b. Phone No. (include area code) 405-552-3622			10. Field and Pool or Exploratory Area Willow Lake				
4. Location of Well (Footage, Sec., T.,R.,M., of 150° FSL & 1980° FEL, SW SE of Sec 19, T24S, R27E)			11. County or Parish, State Eddy, NM				
12. CHECK THE	E APPROPRIATE BO	X(ES) TO INDI	CATE NATURE	OF NOTIC	CE, REPORT OR OTHI	ER DATA	<u> </u>	
TYPE OF SUBMISSION TYPE OF ACTION								
Notice of Intent	Acidize Alter Casing Casing Repair	=	en are Treat Construction	Recla	uction (Start/Resume) amation mplete			
Subsequent Report Change Plans		Plug and Abandon		=	oorarily Abandon	M.I.T.		
Final Abandonment Notice Convert to Injection		Plug I	Plug Back Water Disposal		r Disposal			
testing has been completed. Final Abando determined that the site is ready for final in Attached please find the original Mechanic BLM. Tested the 9 5/8" casing. Shut well in at 06 PSI on 9 5/8" intermediate (pressure was intermediate casing. Pressured up to 500	cal Integrity Test per 5:00 hours, to shut of left on casing after f PSI and ran casing	rformed on the off flow of load v frac). Bled drillir	Preacher 19 Fed water flow from p ng mud off 9 5/8' or BLM. Lost 65	deral 3H o production to no flov	n 4/25/2014 and was casing. Had 340 PS v. Rigged up pump ar minutes. Bled off pres	witnessed by Paul I 5 1/2" SICP after 2 nd pressure recorde	Swartz with the thours and 45 er to the 9 5/8"	
		IG 1 9 2014	Accept	led for IMOCE 8/2				
		ECEIVED	· - -	9/-				
14. Thereby certify that the foregoing is true and Megan Moravec	correct. Name (Printe	a/Typea)	Title Regulator	ry Analyst			· · · <u> </u>	
Signature Theyan Mora			Date 05/06/20	•	ACCEPTE	FOR REC	ORD	
	THIS SPACE	FOR FEDE	RAL OR STA	ATE OF	ICE USE			
Approved by			Title		AUG	Dat 2 2014		
Conditions of approval, if any, are attached. Appithat the applicant holds legal or equitable title to the applicant to conduct operations thereon	ould Office			Rework				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. fictitious or fraudulent statements or representation	Section 1212, make it a	a crime for any pe thin its jurisdiction	erson knowingly an	d willfully t	o make to any departmen CARLSBA	HANY MARKAN AD FIELD OFFICE	ell States any false,	
(Instructions on page 2)							 +	



Order of the Authorized Officer

V

Devon Energy Production Company, LP Precher 19 Federal - 03H API 3001541887, T24S-R27E, Sec 19

August 12, 2014

- 1. This Well's 9 5/8" x 5 ½" casing annulus is required to be monitored for loss of casing integrity. A BLM inspector may request verification of a full annular fluid level at any time.
- 2. Maintain the annulus full of packer fluid at atmospheric pressure. <u>Installation of equipment that will detect failures and display continuous open to the air packer fluid level above the 9 5/8" x 5 ½" annulus vent is required for this production well.</u>
- 3. Notify the BLM's authorized officer ("Paul R. Swartz" <<u>pswartz@blm.gov></u>, cell phone 575-200-7902) to arrange for approval of the annular monitoring system.
- 4. Loss of packer fluid above five barrels per month indicates a developing problem. Notify BLM Carlsbad Field Office, Petroleum Engineering within 5 days.
- 5. A suggested format for monthly records documenting that the casing annulus is fluid filled is available from the BLM Carlsbad Field Office.
- 6. Gain of annular fluid pressure requires notification within 24 hours. Within 30 days install equipment that will maintain a production casing pressure of 0 psia. Notify the BLM's authorized officer ("Paul R. Swartz" cpswartz@blm.gov>, cell phone 575-200-7902). If there is no response phone 575-361-2822.

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

 \S 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.