


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC	229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701		Telephone No.	432-230-0077
Facility Name:	SRO State Unit #48H		Facility Type:	Battery

Surface Owner: State	Mineral Owner:	Lease No. (API#) 30-015-41779
----------------------	----------------	-------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	7	26S	28E	190	North	2080	East	Eddy

Latitude N 32 03.832' Longitude W104 07.130'

NATURE OF RELEASE

Type of Release Oil	Volume of Release Oil 102 bbls	Volume Recovered 35 bbls
Source of Release Oil hauler truck	Date and Hour of Occurrence 8-9-2014 2:15am	Date and Hour of Discovery 8-9-2014 2:15 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Amanda Trujillo	Date and Hour 8-09-2014 8:17 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

While loading the tanker the oil hauler fell asleep and ran over his truck. Vacuum trucks were dispatched to recover any standing fluids.

Describe Area Affected and Cleanup Action Taken.*

The impacted area was approximately 150' x 30' in front of the load-out lines. A third party consultant will be handling this release. The site will be sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By: Approved by District Supervisor:	
Title: Senior Environmental Coordinator	Approval Date: 8/25/14	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 8/25/14	
Date August 22, 2014 Phone: 575-748-6940	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-2A55