

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 03 2014

RECEIVED

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NAB1424726788

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company : Oxy Permian LTD (192463) ✓	Contact : Chris Jones
Address : 1502 W. Commerce, Carlsbad, NM 88220	Telephone No. : 575-628-4121
Facility Name : McKittrick 11-5 SWD Facility	Facility Type: SWD Facility

Surface Owner :	Mineral Owner	Lease No. : NM 53219 API#: 30-015-33611
-----------------	---------------	--

LOCATION OF RELEASE

Unit Letter L	Section 11	Township 22S	Range 24E	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	------------

Latitude 32.40989 Longitude 104.47355

NATURE OF RELEASE

Type of Release : Produced Water	Volume of Release : 100 bbls	Volume Recovered: -0-
Source of Release : Valve malfunctioned	Date and Hour of Occurrence: 8/22/2014	Date and Hour of Discovery: 8/22/2014
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? email: OCD & BLM: Jim Amos	
By Whom? Chris Jones	Date and Hour : 8/25/2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully

Describe Cause of Problem and Remedial Action Taken.*

The valve malfunctioned causing the tanks to overflow releasing 100 barrels of produced water inside the facility. No fluids were recovered. The valve was repaired and the wells put back into service. Talon/LPE was contacted to complete the site assessment. Soil samples were collected to determine appropriate clean up actions.

Describe Area Affected and Cleanup Action Taken.*

The area affected was inside the facility. The impacted area measures approximately 10x80 feet.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones

Printed Name: Chris Jones

Title: HES Specialist

E-mail Address: Christopher_Jones@oxy.com

Date: 8/28/2014 Phone: 575-628-4121

OIL CONSERVATION DIVISION

Approved by District Supervisor:

Approval Date: 9/3/14

Expiration Date: N/A

Conditions of Approval:
Remediation per OCD Rule & Guidelines.

Attached ☐

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/3/14

2RP-2471

* Attach Additional Sheets If Necessary