

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action **NM OIL CONSERVATION**

ARTESIA DISTRICT

SEP 11 2014

RECEIVED

NAB1425532950

OPERATOR

Initial Report Final Report

Name of Company: Clayton Williams <i>25706</i>	Contact: Luis Gonzales
Address: 6-Desta Drive Suite 1100 Midland, TX 79705	Telephone No: 432-661-4708
Facility Name: State 20 B Battery	Facility Type: Battery
Surface Owner: State	Mineral Owner:
Lease No. 3001530918	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County:
A	20	17s	29E					Eddy County

Latitude 32.826973 Longitude -104.088396

NATURE OF RELEASE

Type of Release: Produced Water/Oil	Volume of Release: 55	Volume Recovered: 45
Source of Release: Flow line leak	Date/Hour of Occurrence: 9/9/14	Date/Hour of Discovery: 9/9/14
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Eric Garcia	Date and Hour: 9/10/2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
9/9/2014
The cause of the problem was a leak in the flow line from the battery to the Jenna Com SWD. The line was repaired. Also, vacuum truck removed the standing fluid. Recovered approx... 45 barrels. Hauled the fluid to the disposal. Finally, a crew installed a barb wire fence around the spill site. Pictures of the site were taken for future reports, and a one call was performed.

Describe Area Affected and Cleanup Action Taken.*
The area affected was pasture. The area measures approx.. 2000 sq ft. One call was performed on 9/10/2014 by Republic Backhoe Service LLC. Once the one call clears a backhoe will be used to begin the delineation process. NMOCD will be notified to witness the sampling at the site. The contaminated soil will be hauled off and disposed at R360. Then clean soil will be hauled in to back fill the area. The remediation process will adhere to the NMOCD guideline for spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>DAVE DUNLAP</i>	OIL CONSERVATION DIVISION	
Printed Name: DAVE DUNLAP	Approved by District Supervisor: <i>Mike Bratcher</i>	
Title: Prod. Foreman	Approval Date: 9/12/14	Expiration Date: N/A
E-mail Address: <i>ddunlap@claytonwilliams.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines. Attached	
Date: 9-11-14	Phone: 525-390-2062	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 10/12/14

22P-2483