

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT Form C-141
Revised August 8, 2011

SEP 15 2014
Submit a copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 143 593 6900

| | | | | |
|---|--|----------------------------|--|--|
| Name of Company: COG Operating LLC <i>217955</i> | | OPERATOR | <input checked="" type="checkbox"/> Initial Report | <input checked="" type="checkbox"/> Final Report |
| Address: 600 West Illinois Avenue, Midland TX 79701 | | Contact: Robert McNeill | | |
| Facility Name: Momba 24 Federal Com #3 | | Telephone No. 432-230-0077 | | |
| | | Facility Type: Battery | | |
| Surface Owner: Federal | | Mineral Owner: Federal | API No. 30-015-40946 | |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| B | 24 | 26S | 28E | 43 | North | 2180 | East | Eddy |

Latitude N32°02.102' Longitude W104°02.353'

NATURE OF RELEASE

| | | |
|--|---|--|
| Type of Release: Oil and Produced Water | Volume of Release: 3 bbls Oil; 250 bbls PW | Volume Recovered: 3 bbls Oil; 247 bbls PW |
| Source of Release: Water tank | Date and Hour of Occurrence: 9/14/2014 1:00 pm | Date and Hour of Discovery: 9/14/2014 1:00 pm |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Mike Bratcher -- NMOCD ; Jim Amos - BLM | |
| By Whom? Amanda Trujillo | Date and Hour: 9/15/2014 5:00 pm | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The nipple on the water tank load line broke causing the discharge of fluid. Repairs were made and the tank was put back into production.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within a lined facility. Vacuum trucks were dispatched to recover standing fluid and dispose of at an NMOCD approved facility. Impacted gravel was excavated, the area was pressure washed and the gravel was replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|--|-----------------------------------|
| Signature: <i>Atujillo</i> | OIL CONSERVATION DIVISION | |
| Printed Name: Amanda Trujillo | Approved by Environmental Specialist: <i>[Signature]</i> | |
| Title: Senior Environmental Coordinator | Approval Date: <i>9/16/14</i> | Expiration Date: <i>NA</i> |
| E-mail Address: atrujillo@concho.com | Conditions of Approval: <i>Final</i> | Attached <input type="checkbox"/> |
| Date: September 15, 2014 | Phone: 575-748-6940 | |

* Attach Additional Sheets If Necessary

2RP-2486