

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

SEP 16 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NA B1425952396 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <u>260737</u>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: South Loop 10" SWD Mainline. The spill location was 1,608 ft. east of the PLU-CVX-JV-BS #021H	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-41554
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	13	25S	30E					Eddy

Latitude N 32.124577 Longitude W 103.835877

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 384 bbls.	Volume Recovered: 10 bbls.
Source of Release: 10" Poly pipe	Date and Hour of Occurrence: 9/6/14 time unknown	Date and Hour of Discovery 9/6/13 at 7:30 a.m. <u>9/6/14?</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Emergency #104 and Jim Amos "BLM"	
By Whom? Tony Savoie	Date and Hour: 9/6/14 at 2:17 p.m.	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* The spill traveled approximately 120 ft. and ponded up in a low lying area consistent with the definition of a playa lake. At the time of review at 3:00 p.m. on 9/6/14 the only water standing in the playa area was produced water from the spill. However over the course of the next 2 days approximately 3 inches of rain fell.

Describe Cause of Problem and Remedial Action Taken.*

A weld failed on the poly pipe. The affected portion of pipe was isolated by block valves located to the north and south of the release point. The section of pipe with the failed weld was cut out and replaced on 9/8/14.

Describe Area Affected and Cleanup Action Taken.*

Approximately 10 bbls of water was recovered at the release point. The remainder of the fluid soaked into the ground. The release impacted approximately 720 sq.ft. of pipeline right of way and approximately 14,310 sq.ft. of pasture area. Samples were collected on 9/10/14 by Basin Env. From the point of release and the ponded areas. The area impacted by the release will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Waste Management and Remediation Specialist		Approval Date: <u>9/16/14</u>	Expiration Date: <u>NA</u>
E-mail Address: tasavoie@basspet.com		Attached <input type="checkbox"/>	
Date: <u>9/16/14</u> Phone: 432-556-8730		Conditions of Approval: Remediation per OCD Rule & Guidelines.	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/16/14

2RP-2189