

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

SEP 22 2014

Form C-141  
Revised October 10, 2003

RECEIVED  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

## Release Notification and Corrective Action

NAB142-0550986

Name of Company <u>Buckeye Disposal 222759</u>		Contact <u>Terry Wallace</u>	
Address <u>PO 2224 Lubbock TX 79400</u>		Telephone No. <u>575-390-6167</u>	
Facility Name <u>NM DU SH #1 SWD</u>		Facility Type <u>Salt Water Disposal</u>	

Surface Owner	Mineral Owner	Lease No. <u>30-D15-24531</u>
---------------	---------------	-------------------------------

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

## NATURE OF RELEASE

Type of Release <u>Water Residue</u>	Volume of Release <u>700 bbls</u>	Volume Recovered <u>3000 bbls</u>
Source of Release <u>Lightning Strike</u>	Date and Hour of Occurrence <u>Sept. 19, 2014 5:00pm</u>	Date and Hour of Discovery <u>Same</u>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Thunderstorm strike by lightning. Storm in the area had dropped between 12"-20" of rain in 2 week period. Day before storm approximately 6-8" of rain.

Describe Area Affected and Cleanup Action Taken.\*

Location Dyke and Pad. - Vacuum trucks sucked up fluids in dyke and pad. Approximately 3000 bbls. Evaluating some fluids on pasture. Pasture approximately 200 bbls (Rain)

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>T. Wallace</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Terry Wallace</u>	Signed By <u>Mike Brannon</u>	
Title: <u>Manager</u>	Approved by District Supervisor:	
E-mail Address: <u>terry.wallace@state.nm.gov</u>	Approval Date: <u>9/22/14</u>	Expiration Date: <u>N/A</u>
Date: <u>9-22-14</u> Phone: <u>575-390-6167</u>	Conditions of Approval: Remediation per OCD Rule & Guidelines.	

\* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 10/22/14

2RP-2505