


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1426849862

Name of Company Yates Petroleum Corporation		OGRID Number 25575	Contact Robert Asher	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address 104 S. 4 th Street		Telephone No. 575-748-1471			
Facility Name Bailout BOA Federal Com. #1		Facility Type Battery			
Surface Owner Federal		Mineral Owner Federal		API No. 30-015-37169	

LOCATION OF RELEASE

30-015-37169

Unit Letter I	Section 12	Township 18S	Range 29E	Feet from the 1770	North/South Line South	Feet from the 410	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.75940 Longitude 104.02041

NATURE OF RELEASE

Type of Release Oil	Volume of Release 5 B/O	Volume Recovered 5 B/O
Source of Release Production Tank	Date and Hour of Occurrence 8/17/2014; AM	Date and Hour of Discovery 8/17/2014; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Oil tank overflowed because equalizer line was closed, causing the release. Vacuum truck(s) were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 5'X 10'. All released oil was recovered using a vacuum truck. Battery is bermed and lined. Tank pressure washed. Depth to Ground Water: >100' (approximately 150', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on all oil recovered and battery is lined, Yates Petroleum Corporation requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Asher</i>	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by Environmental Specialist <i>Mike Brown</i>	
Title: NM Environmental Regulatory Supervisor	Approval Date: <i>9/25/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: September 23, 2014	Phone: 575-748-4217	2RP-

* Attach Additional Sheets If Necessary

2RP-2512