

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised October 10, 2003

OCT 01 2014

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

NAB1427530587

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company : Hanson Trucking Inc. <u>229137</u>	Contact: Mathew Bertoch
Address: 1782 W. 1760 S. Suite A Roosevelt UT 84066	Telephone No. (435) 722-1891
Facility Name: Submarine 10 Federal 2H Battery	Facility Type: Well Lease

Surface Owner : Concho	Mineral Owner :BLM	Lease No. NMLC-028731B
------------------------	--------------------	------------------------

LOCATION OF RELEASE

30-015-40358

Unit Letter A	Section 10	Township 17S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.85385 Longitude 104.05412

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 11.0 BBLs	Volume Recovered 0
Source of Release Truck loading on location.	Date and Hour of Occurrence 9/29/2014 10:55 PM	Date and Hour of Discovery 9/30/2014 10:55 AM
Was Immediate Notice Given? Yes <input checked="" type="checkbox"/> No Not Required	If YES, To Whom? Richard Conrad	
By Whom? Dancel Ahquin	Date and Hour 9/30/2014 12:31 AM	
Was a Watercourse Reached? Yes No <input checked="" type="checkbox"/>	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Driver overfilled semi-trailer while loading crude oil. Driver stopped loading process, shut off pump and closed tank valve. Supervisor was immediately notified.

Describe Area Affected and Cleanup Action Taken.* Spill was contained to the pad. Madron Services Inc. was contacted at 11:52 AM to clean up spilled crude oil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Mathew Bertoch</u>	OIL CONSERVATION DIVISION	
Printed Name: Mathew Bertoch	Approved by District Supervisor: <u>Handwritten Signature</u>	
Title: Operation Manager	Approval Date: <u>10/1/14</u>	Expiration Date: <u>NA</u>
E-mail Address: hansontrucking@ubtanet.com	Conditions of Approval	Attached <input type="checkbox"/>
Date: 9/30/14	Remediation per O.C.D. Rules & Guidelines	

Phone: (435) 671-9755

* Attach Additional Sheets If Necessary

REMIT REMEDIATION PROPOSAL NO
LATER THAN: 11/1/14

2RP-2517