

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

# NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

OCT 02 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

NAB142250488

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Shawnee Federal Battery	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-30628
------------------------	------------------------	----------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	15	17S	30E	1650'	South	2310'	East	Eddy

Latitude N32 49.903' Longitude W103 57.542'

### NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 20 bbls	Volume Recovered: 18 bbls
Source of Release: Valve	Date and Hour of Occurrence: 9/21/2015 8:00 am	Date and Hour of Discovery: 9/21/2015 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The release was caused by a valve on circulating pump. The valve was slightly opened resulting in the release. A vacuum truck was dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.\*

The release was contained inside the bermed area. A crew was dispatched to remove impacted soil. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature:

*Amanda Trujillo*

Printed Name: Amanda Trujillo

Approved by Environmental Specialist:

*[Signature]*

Title: Senior Environmental Coordinator

Approval Date: 10/2/14

Expiration Date: NA

E-mail Address: atrujillo@concho.com

Conditions of Approval:

Attached ☐

Date: October 2, 2014

Phone: 575-748-6940

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 11/2/14

\* Attach Additional Sheets If Necessary.

2 RP-2520