NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

accordance with 19.15.29 NMAC.

Subr**RECEIVE** Depropriate District Office in

OCT 0 6 2014

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

Attach Additional Sheets If Necessary

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

State of New Mexico

Energy Minerals and Natural Resources

Release Notification and Corrective Action **OPERATOR** Final Report Name of Company: Mewbourne Oil Company Contact: Zack Thomas Address: PO Box 5270 Hobbs NM 88241 Telephone No. 575-393-5905 Facility Type: SWD Facility Name: San Lorenzo SWD #001 API No. 30-015-23067 Mineral Owner: Surface Owner: State LOCATION OF RELEASE Feet from the Township North/South Line Feet from the East/West Line County Unit Letter Section Range 1140 Н 34 258 28E 2450' North East Eddy Latitude 32.08707 Longitude -104.06766 NATURE OF RELEASE Volume of Release: estimated Volume Recovered: Oil (253 bbls) Type of Release: Produced water/Oil 1726 bbls total fluid (1473 bbls PW/rain water (267 bbls) 2536615. (11) Source of Release: Damaged 4" SDR7 poly line Date and Hour of Discovery Date and Hour of Occurrence 9-26-14 9-28-14 5:00 pm If YES, To Whom? Was Immediate Notice Given? ☑ Yes ☐ No ☐ Not Required Mike Bratcher By Whom? Date and Hour 9-28-14 6:50 pm If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? ✓ Yes
✓ No 1726 bbls If a Watercourse was Impacted, Describe Fully.* SWD line ran alongside west side highway 285 from the San Lorenzo SWD to the Delaware Ranch SWD was damaged in the draw between mile marker 6 and mile marker 7 under bridge while draw was flowing. Describe Cause of Problem and Remedial Action Taken.* Debris and flood waters caused damage to poly line underneath bridge. The line was capped off on the 9-28-2014 stopping the release. Describe Area Affected and Cleanup Action Taken.* Affected area- The draw was affected from the bridge at highway 285 to approximately six thousand feet east down the draw, small remnants of oil believed to be from the same release were found an additional six thousand feet down the draw. Mewbourne Oil Company has recovered 253 bbls of oil from the area with vacuum trucks and skimmers, and is continuing cleanup efforts via hydrocarbon absorbing pads and booms across the flowing draw. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature Signed By Approved by Environmental Specialist Printed Name: Zack Thomas Title: Environmental Rep. Approval Date. **Expiration Date** E-mail Address: zthomas@mewbourne.com Conditions of Approval: Attached [Remediation per O.C.D. Rules & Guidelines Date: 10-3-14 Phone: 575-602-21

WEMIT REMEDIATION PROPOSAL NO

ATER THAN: