

OCT 08 2014

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Poker Lake Unit 347H	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-38668	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	11	25S	30E	540	North	1440	West	Eddy

Latitude N 32.15100 Longitude W 103.85560

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 65 bbls crude oil and 12 bbls produced water	Volume Recovered: 5 bbls crude oil and 2 bbls of produced water with 40 bbls rain water.
Source of Release: A 2" hammer union on the wellhead	Date and Hour of Occurrence: 9/20/14 time unknown	Date and Hour of Discovery: 9/20/14 at approximately 10:50 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? First reported to EH&S at 11:56 a.m. as 5 bbls crude oil floating on rain water. Could not access until 8:00 a.m. on 9/22/14 due to heavy flooding. Reported correction and release amount to Heather in person 8:00 a.m. on 9/22/14.	
By Whom? Tony Savoie	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A hammer union leaked on the wellhead, the connection was re-tightened.		
Describe Area Affected and Cleanup Action Taken.* The release impacted approximately 27,200 sq.ft. of caliche well pad and lease road and approximately 53,700 sq.ft. of pasture area that was flooded with a combination of rain water and crude oil. The entire impacted area was sampled on 9/24/14. The crude oil impacted area was treated twice with micro-blaze on 9/26/14. The chloride impacted area on the pad will be excavated and replaced with clean caliche. The pasture area will be re-sampled and remediated as necessary.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: 10/8/14	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/7/14	Remediation per O.C.D. Rules & Guidelines	
Phone: 432-556-8730	SUBMIT REMEDIATION PROPOSAL NO	
	LATER THAN: 11/8/14	

* Attach Additional Sheets If Necessary

2RP-2527