

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

OCT 13 2014
Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1428741156		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: COG Operating LLC		Contact: Robert McNeill		
Address: 600 West Illinois Avenue, Midland TX 79701		Telephone No. 432-230-0077		
Facility Name: Michalada Federal #3D		Facility Type: Battery		
Surface Owner: Federal		Mineral Owner: Federal	API No. 30-015-35157	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	3	22S	25E	990'	North	2287'	East	Eddy

Latitude 32.4255574702987 Longitude -104.382694970657

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 311 bbls Oil	Volume Recovered: 100 bbls Oil
Source of Release: Tank Battery	Date and Hour of Occurrence: 9/26/2014 8:03 pm	Date and Hour of Discovery: 9/26/2014 8:03 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD ; Jim Amos - BLM	
By Whom? Amanda Trujillo	Date and Hour: 9/29/2014 6:54 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



This release was caused by a hole in the tank bottom. Vacuum trucks were dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred with the bermed area, fluids were contained within the bermed area. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Amanda Trujillo	Approval Date: 10/14/14	Expiration Date: NA
Title: Senior Environmental Coordinator	Conditions of Approval:	
E-mail Address: atrujillo@concho.com	Attached <input type="checkbox"/>	
Date: October 13, 2014 Phone: 575-748-6940	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 11/14/14

* Attach Additional Sheets If Necessary

2BP-2547