

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

OCT 13 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1424526532

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Randall Federal #3	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-38389
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 7	Township 17S	Range 30E	Feet from the 330'	North/South Line South	Feet from the 990'	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.842797221899 Longitude -104.006025554343

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 10 bbls Oil; 20 bbls PW	Volume Recovered: 0 bbls Oil; 15 bbls PW
Source of Release: Fire tube in heater treater	Date and Hour of Occurrence: 9/27/2014 7:00 am	Date and Hour of Discovery: 9/27/2014 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mr. Bratcher - OCD / Jim Amos - BLM	
By Whom? Amanda Trujillo	Date and Hour: 9/29/2014 6:43 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The release was caused by a hole in the fire tube which resulted in a fire. Fire crews were called to put out the fire and vacuum trucks dispatched to pick up standing fluid.

Describe Area Affected and Cleanup Action Taken.*
The release occurred within a lined facility. All standing fluids were removed and disposed of at an NMOCD approved facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>A Trujillo</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Amanda Trujillo	Approval Date: <i>10/21/14</i>	Expiration Date: <i>NA</i>
Title: Senior Environmental Coordinator	Conditions of Approval: <i>Final</i>	
E-mail Address: atrujillo@concho.com	Attached <input type="checkbox"/>	
Date: October 13, 2014	Phone: 575-748-6940	

* Attach Additional Sheets If Necessary

2RP-2502