


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report

X Final Report

Name of Company	BOPCO, LP	Contact	Tony Savoie
Address	522 W. Mermod, Suite 704, Carlsbad, NM 88220	Telephone No.	(432)556-8730
Facility Name	Indian Flats Bass Federal #3	Facility Type	E&P
Spill location is 2300 ft. east of well location.			

Surface Owner	Federal	Mineral Owner	Federal	Lease No.	API #30-015-21853
---------------	---------	---------------	---------	-----------	-------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	35	21S	28E					Eddy

Latitude 32.433821° North

Longitude 104.057298° West

NATURE OF RELEASE

Type of Release	Crude oil and produced water	Volume of Release	1 bbl of crude oil and 17 bbls of produced water	Volume Recovered	1 bbl total fluid
Source of Release	3" poly flow line	Date and Hour of Occurrence	5/7/13 Hour unknown	Date and Hour of Discovery	5/7/13 at 9:00 a.m.
Was Immediate Notice Given?	X Yes No Not Required	If YES, To Whom?	Jim Amos with the BLM		
By Whom?	Tony Savoie	Date and Hour	5/7/13 5:00 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken:* The 3" poly flow line split. The damaged area was cut out, and the pipe was fused back together.

Describe Area Affected and Cleanup Action Taken.* Approximately 360 sq. ft. of lease road, and approximately 1800 sq. ft. of pasture land. A vacuum truck was utilized to remove all of the free-standing liquid. Following initial response activities, both releases were remediated as per NMOCD recommended guidelines. Please reference the attached *Remediation Summary & Site Closure Request* for remediation details.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by District Supervisor:	
Title:		Approval Date: 8/4/14	Expiration Date: NA
E-mail Address:		Conditions of Approval: Final	
Date: 10/3/13	Phone:		

2RP-1659