

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**NM OIL CONSERVATION**  
State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

ARTESIA DISTRICT

OCT 24 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141  
Revised August 8, 2011

RECEIVED

**Release Notification and Corrective Action**

NAB 430049948

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: West Brushy 8 Federal SWD #1	Facility Type: SWD

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31675
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter A	Section 8	Township 26S	Range 29E	Feet from the 660	North/South Line North	Feet from the 330	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.0625249053514 Longitude -103.99867482237

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 900 bbls	Volume Recovered: 800 bbls
Source of Release: Water tank overflow	Date and Hour of Occurrence: 10/10/2014 7:30 am	Date and Hour of Discovery: 10/10/2014 7:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD / James Amos - BLM	
By Whom? Amanda Trujillo	Date and Hour: 10/10/2014 5:46 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Human error. The battery was down for repair due to a pump failure with a well watcher on site to maintain well. Vacuum truck trucks were dispatched to remove all standing fluid.

Describe Area Affected and Cleanup Action Taken.\*

The majority of the impact was contained within the lined facility. Approximately 225'x100' was impacted outside the containment. All standing fluids were picked up and disposed of at an NMOCD approved facility. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 10/27/14	Expiration Date: NA
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: October 24, 2014 Phone: 575-748-6940	Remediation per O.C.D. Rules & Guidelines	

Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 11/27/14

2RP-2566