

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION** Form C-141  
ARTESIA DISTRICT Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-276 The spill is located 2,760 ft. N.E. of the well pad location in Section 12-24S-29E (2RP-2298)	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-35137	

**LOCATION OF RELEASE**




Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	12	24S	29E	45	South	15	East	Eddy

Latitude N 32.224862 Longitude W 103.929663

**NATURE OF RELEASE**

Type of Release: Crude oil and produced water	Volume of Release: 7 bbls. crude oil and 3 bbls produced water	Volume Recovered: None
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence: 4/30/14 approximately 9 a.m.	Date and Hour of Discovery: 4/30/14 at 10 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* An unknown vehicle ran over the flow line "swing" where the line turns west to head to the tank battery. The well was shut in and the broken fitting was replaced.		
Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 1,740 sq.ft. of pasture alongside the road way in the flow line right of way and approximately 700 sq.ft. of lease road. The saturated soil was scraped up with a backhoe and shovels and stockpiled on-site. <b>Basin Environmental began the remediation effort on 9/11/14 and completed 10/3/14. Approximately 120 cubic yards of soil was disposed of at Lea Land. Please reference the Soil Closure Request date October, 2011.</b>		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: 	
Title: Waste Management and Remediation Specialist	Approval Date: 10/27/14	Expiration Date: NA
E-mail Address: tasavoie@basspet.com	Conditions of Approval: 	Attached <input type="checkbox"/>
Date: 10/27/14	Phone: 432-556-8730	

\* Attach Additional Sheets If Necessary

2RP-2298