

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

OCT 31 2014

Form C-141
Revised August 8, 2011

Submit to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1430942528

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Hunt Cimarron Limited Partnership	Contact Richard C. Gilliland
Address P.O. Box 1592, Roswell, NM 88202	Telephone No. (575) 623-9799
Facility Name Anchor Deep Unit Water Transfer Line	Facility Type Exploration and Production

Surface Owner Federal - BLM	Mineral Owner Federal	API No. 30-005-00433
-----------------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	4	14-S	29-E					Chaves

Latitude 3.134287 Longitude -104.03436

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 80 Bbls (est)	Volume Recovered None
Source of Release 3" Poly Pipe Water transfer line	Date and Hour of Occurrence	Date and Hour of Discovery 4PM 10/22
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? 10/23 notified BLM and Grazing Lessee	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted. Describe Fully.*

N/A



Describe Cause of Problem and Remedial Action Taken.*

Failure in 3" poly-pipe water transfer line. Water transfer was immediately shut in and affected section of transfer line was repaired/replaced.

Describe Area Affected and Cleanup Action Taken.*

Sandy dune area approximately 2,500 sq. ft. All water soaked into sand. Will be remediated as per requirements of NMOCD and BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Richard C. Gilliland	Signed By  Approved by Environmental Specialist:	
Title: Vice President	Approval Date: 11/5/14	Expiration Date:
E-mail Address: richard.gilliland@huntcompanies.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/27/2014 Phone: 623-9799	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 12/5/14

2RP-2519