

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

NOV 04 2014

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1430936021

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: State MO #1 SWD	Facility Type: SWD

Surface Owner: State	Mineral Owner:	API No. 30-015-24344
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	27	17S	28E	1320	North	1320	West	Eddy

Latitude 32.809143728368 Longitude -104.168101290571

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 350 bbls	Volume Recovered: 348 bbls
Source of Release: Filter pot	Date and Hour of Occurrence: 10-15-2014 12:00 pm	Date and Hour of Discovery: 10-15-2014 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 10-16-2014 7:57 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

A filter pot became plugged and burnt the seal on the pump which caused the release. Vacuum trucks were dispatched to recover standing fluid and dispose of at an NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred with a lined facility. Once fluids were recovered the area was cleaned and returned to normal operations.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By:  Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 11/4/14	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: November 3, 2014 Phone: 575-748-6940		

\* Attach Additional Sheets If Necessary

2RP-2578