

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

OCT 02 2014

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

NAB1430851048

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Cabo Wabo 25 Federal #1H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-40440
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 25	Township 25S	Range 29E	Feet from the 330'	North/South Line North	Feet from the 600'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.1072402109889 Longitude -103.944639787162

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 120 bbls	Volume Recovered: 115 bbls
Source of Release: Lightning struck water tank	Date and Hour of Occurrence: 9/19/2014 4:30	Date and Hour of Discovery: 9/19/2014 4:30
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Robert McNeill	Date and Hour: 9/22/2014 8:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

During the flooding, lightning struck the water tank and caused a fire. Due to the flooding fire crews were unable to reach the location. The fire burned itself out. Fluids were contained within the lined berm, vacuum trucks were dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.*

The release was contained within the lined bermed area. A new tank will be placed in the facility and it will be returned to previous working condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Amanda Trujillo

Title: Senior Environmental Coordinator

E-mail Address: atrujillo@concho.com

Date: October 2, 2014

Phone: 575-748-6940

Approved by Environmental Specialist

Approval Date: 11/4/14

Conditions of Approval:

FINAL

Expiration Date: N/A

Attached ☐

* Attach Additional Sheets If Necessary

2RP-2573