NM OIL CONSERVATION ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S: First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

NOV 1 0 2014

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action												
NAB14	3145		OPERA	ror			al Report		Final Report			
Name of Co			Contact	Zack Laird								
Address Facility Nat	210 Parl		Telephone No. 405-742-2696 Facility Type Oil and Gas Well									
Surface Ow	ner Feder)wner	Federal API No. 30-015-24875									
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/V	West Line County			
P	27	26S	29E		690 FS	SL _		660FE	EL	Eddy		
Latitude_32.0072945706848												
Type of Rele		Volume of Release 25Bbls Volume Recovered 25Bbls										
Source of Release Transfer Pump Suction Line Leak						Date and Hour of Occurrence Date and Hour of Discovery						
Was Immediate Notice Given?						11/10/14 - prior to 0800hrs MT 11/10/14 - 0800hrs MT If YES, To Whom?						
☐ Yes ☐ No ☐ Not Required						Heather Patterson (Voicemail on mobile)						
By Whom? Zack Laird - Sr. EHS Manager						Date and Hour 11/10/14 - 1727hrs (CT) 4:43pm * attacher						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Pully.* N/A												
Describe Cause of Problem and Remedial Action Taken.*												
Transfer pump suction line from tank battery developed a leak and released 25Bbls of produced water to lined secondary containment. A vacuum truck												
was used to recover free liquids. The suction line, formerly rubber hose construction, will be replaced with steel line.												
Describe Area Affected and Cleanup Action Taken.*												
All fluid rema	ined in lined	d secondary c	ontainmen	t and was able to	be recov	ered with vac	cuum truck.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all	operators as	re required to	report and	l/or file certain rel of a C-141 repor	lease not	tifications and	perform correcti	ve actio	ons for rele	ases which n	iay end	danger
				investigate and re								
or the environn	nent. In add	dition, NMOC	D accepta	ance of a C-141 re	port doe	s not relieve	the operator of re-	sponsib	ility for co	mpliance wit	h any	other
federal, state, o	i tocat taws	androi regui	mons.				OIL CONS	ERVA	ATION I	DIVISION	J	
Ciamatuma.	//		OIL COIVE	DIX V I	. /	DIVISIO						
Signature: Printed Name: Zack Laird						Approved by Environmental Specialist:						
Title: Sr. EHS		·	,		A.	oproval Date:	11/12/14	/ E-	epiration D	ata: All	 1	
								ipharon Date.				
L-man riduress. Zuand@rkixp.com							onditions of Approval:					
Date: 11/10/14	1		Phone: 4	05-987-2213								