

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

NOV 06 2014

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1431053789

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: West Brushy 5 Federal SWD #5	Facility Type: SWD

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31869
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	5	26S	29E	800	South	850	East	Eddy

Latitude 32.0665385200141 Longitude -104.000346200798

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 225 bbls	Volume Recovered: 220 bbls
Source of Release: Flowline	Date and Hour of Occurrence: 10-16-2014 7:30 pm	Date and Hour of Discovery: 10-16-2014 7:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD / Jeffery Robertson - BLM	
By Whom? Amanda Trujillo	Date and Hour: 10/17/2014 4:40 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

An over pressured a poly flowline caused the release. Vacuum trucks were dispatched to pick up standing fluid and the flowline was repaired. All fluids were disposed of at an NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.*

The impacted area was in the pasture approximately a half mile long and 2' wide. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 11/6/14	Expiration Date: NA
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: November 5, 2014	Remediation per O.C.D. Rules & Guidelines	
Phone: 575-748-6940	SUBMIT REMEDIATION PROPOSAL NO	

LATER THAN: 12/10/14

* Attach Additional Sheets If Necessary

2RP-2586