## **NM OIL CONSERVATION**

District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Santa Fe, NM 87505

ARTESIA DISTRICT

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr.

NOV 1 2 2014

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

			Kel	ease Notific	catio	on and Co	orrective A	ction				
DAB14	3173	1250			OPERATOR			Initi	al Report	Final Repo		
Name of Company Oxy Permian Ltd. 193410.3						Contact Christopher Jones						
Address 1502 W. Commerce Dr., Carlsbad, NM						Telephone No. (575) 628-4121						
Facility Name James Buchanan CTB						Facility Type Battery						
Surface Owner State Mineral Owner						API No. 30-015-29890						
Builde O W	nor State	<del></del>	·			111110. 30-013 23050						
Unit Letter   Section   Township   Range   Feet from the   North/South Line   Feet from the   East/West Line   County												
Unit Letter	Section	Township	Range	Feet from the	Nort	h/South Line	/South Line   Feet from the			County		
I	33	. 185	28E							Eddy County, NM		
Latitude N 32.70211° Longitude W 104.17430°												
NATURE OF RELEASE												
Type of Relea						~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~			Recovered 0 bbls			
Source of Release Corrosion of 3" steel line						Date and H				Hour of Discovery		
Was Immediate Notice Given?							If YES, To Whom?					
Yes No Not Required Mike Bratcher, Heather Patterson-NMOCD												
By Whom?	Kathy Pur	rvis, BBC Inte			Date and Hour 11/10/2014 @ 12:26 pm							
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
			No			•						
If a Watercourse was Impacted, Describe Fully.*												
·					•							
Describe Cause of Problem and Remedial Action Taken.*												
Corrosion of a	3" steel lin	ne leaked 15 b	bls of oil	onto the ground. 1	No flu	ids were recove	ered and the line v	was repaired	l/replac	ed.		
Describe Area	Affected o	nd Cleanup A	ction Take	an *		<del></del>	<del></del>					
The affected a	rea is appro	ximately 15'	x 20' on 1	ocation. Remedia	tion w	rill be complete	ed in accordance w	vith a plan a	nnrove	d by NMOCD.		
							•	,				
I hereby certify	y that the in	formation giv	en above	is true and comple	ete to t	the best of my l	knowledge and un	derstand the	at pursi	ant to NMOCI	O rules and	
regulations all	operators a	re required to	report and	der file pertain re	lease r	notifications and	d perform correct	ive actions t	for rele	ases which may	/ endanger	
public health or the environment. The acceptance of a C 141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to acceptance under the environment.												
or the environment. In addition, NMOOD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state, o	or local law	and or regul	ations.									
						OIL CONSERVATION DIVISION						
Signature:	1/2											
Printed Name: Christopher Jones						Approved by District Supervisor:						
Title: HES S	pecialist				Approval Date: 1//13/14 Expiration Date: NA							
E-mail Address	s: Christo	pher_Jones@			Conditions of Approval:							
Date: //- 1/-	-14		Phone:	(575) 628-4121		1				Attached		
والمالية المصلية	1 /C1	TC NT										

2RP-2596