

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

DEC 01 2014

Form C-141  
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**NABK33649200**

<b>NAME OF COMPANY</b> Yates Petroleum Corporation		<b>OGRID Number</b> 25575	<b>CONTACT</b> Amber Cannon	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
<b>Address</b> 104 S. 4 <sup>th</sup> Street		<b>Telephone No.</b> 575-748-1471		
<b>Facility Name</b> Cutter APC #2H		<b>Facility Type</b>		
<b>Surface Owner</b> Fee		<b>Mineral Owner</b> Fee	<b>API No.</b> 30-015-41786	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	21	19S	25E	551	South	95	West	Eddy

Latitude 32.64054 Longitude 104.49753

**NATURE OF RELEASE**

<b>Type of Release</b> Produced Water	<b>Volume of Release</b> 20 B/PW	<b>Volume Recovered</b> 18 B/PW
<b>Source of Release</b> Poly line	<b>Date and Hour of Occurrence</b> 11/21/2014; AM	<b>Date and Hour of Discovery</b> 11/21/2014; AM
<b>Was Immediate Notice Given?</b> <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	<b>If YES, To Whom?</b> N/A	
<b>By Whom?</b> N/A	<b>Date and Hour</b> N/A	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse.</b>	
<b>If a Watercourse was Impacted, Describe Fully.*</b>		
<b>Describe Cause of Problem and Remedial Action Taken.*</b> The poly line busted, causing the release. Vacuum truck(s) and roustabout crew was called.		
<b>Describe Area Affected and Cleanup Action Taken.*</b> An approximate area of 10' X 10' around tin horns near a battery. The poly line was replaced and the vacuum truck removed standing fluid (18 B/PW). Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. <b>Depth to Ground Water: 50-99' (approximately 50-75', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: &gt;1000', SITE RANKING IS 10.</b>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
<b>Signature:</b> <u>Amber Cannon</u>	<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Amber Cannon	<b>Signed By:</b> <u>Mike Brannon</u> Approved by Environmental Specialist:	
<b>Title:</b> NM Environmental Regulatory Agent	<b>Approval Date:</b> <u>12/2/14</u>	<b>Expiration Date:</b> <u>N/A</u>
<b>E-mail Address:</b> ACannon@yatespetroleum.com	<b>Conditions of Approval:</b>	
<b>Date:</b> December 1, 2014	<b>Remediation per O.C.D. Rules &amp; Guidelines</b> <b>SUBMIT REMEDIATION PROPOSAL NO</b> <b>LATER THAN:</b> <u>11/21/15</u>	
<b>Phone:</b> 575-748-4111	<b>Attached</b> <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-263A