

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: PLU-162 (2RP-2265)	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-35522

LOCATION OF RELEASE

Unit Letter C	Section 6	Township 24S	Range 30E	Feet from the 660	North/South Line North	Feet from the 1855	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N 32.252159 Longitude W 103.923572

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 400 bbls	Volume Recovered: None
Source of Release: 1" hose on the water injection line	Date and Hour of Occurrence: 4/20/14 time unknown	Date and Hour of Discovery 4/20/14 at 5:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104 and the BLM	
By Whom? Tony Savoie	Date and Hour: 4/20/14 at 9:00 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION

ARTESIA DISTRICT

DEC 09 2014

Describe Cause of Problem and Remedial Action Taken.*

A 1" high pressure hose connecting the flow line to the well failed at the coupling. The hose section was replaced.



RECEIVED

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 22,500 sq.ft. of well pad area and approximately 15,000 sq.ft. of pasture area. The site was cleared by the BLM Arch survey. Basin Environmental began delineation activities on 4/21/14 and started removing impacted soil on 4/22/14. *The final on-site remediation ended on 6/18/14, Basin environmental excavated all contaminated soil as deemed practicable during the effort and hauled approximately 6060 cubic yards of soil to Lea Lands for disposal, approximately 6,620 cubic yards of clean purchased soil was hauled back to the site Please reference the Site Closure Request dated October 2014 for details.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Tony Savoie	Approval Date: 12/15/14	Expiration Date: NA
Title: Waste Management and Remediation Specialist	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
E-mail Address: tasavoie@basspet.com		
Date: 12/9/14	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

2RP-2265