

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

DEC 15 2014

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1435032750

Name of Company <i>Cimarex Energy</i>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address <i>600 N Marienfeld Ste 600 Midland TX</i>		Contact <i>Christine Alderman</i>		
Facility Name <i>Nitro 11 Fed 2H</i>		Telephone No. <i>432-853-7059</i>		
Facility Type <i>Production</i>				
Surface Owner	Mineral Owner	API No. <i>30-015-36100</i>		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	11	16S	29E	375	N	660	E	Eddy

Latitude *32.9409* Longitude *-104.05300*

NATURE OF RELEASE

Type of Release <i>Produced water and crude</i>	Volume of Release <i>80 bbls PW and 2 bbls crude</i>	Volume Recovered <i>0 bbls PW and 0 bbls crude</i>
Source of Release <i>valve on water stock tank failed</i>	Date and Hour of Occurrence <i>11/17/14</i>	Date and Hour of Discovery <i>11/17/14</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Mike Bracher/Sol Hughes</i>	
By Whom? <i>Christine Alderman</i>	Date and Hour <i>11/18/14</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* <i>The water valve on the front of the PW tank failed and released fluids into a lined containment. No fluids were recovered due to heavy amount of soil on top of liner.</i>		
Describe Area Affected and Cleanup Action Taken.* <i>All impacted soils were removed from on top of the liner and replaced.</i>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Christine Alderman</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Christine Alderman</i>	Approved by Environmental Specialist: <i>Mike Bracher</i>	
Title: <i>ESH Supervisor</i>	Approval Date: <i>12/15/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>calderman@cimarex.com</i>	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: _____ Phone: <i>432-853-7059</i>		

* Attach Additional Sheets If Necessary

2RP-2659