

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**NAB1435037409** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <b>8100737</b>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: ND 19 Federal SWD No.001	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-39713
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	19	24S	30E	516	North	705	East	Eddy

Latitude N 32.208897 Longitude W 103.914495

**NATURE OF RELEASE**

Type of Release: Produced water	Volume of Release: 226 bbls.	Volume Recovered: 85 bbls.
Source of Release: Flex gasket on wellhead	Date and Hour of Occurrence: 12/3/14 at approximately 7:30 am	Date and Hour of Discovery: 12/3/14 at approximately 7:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD	
By Whom? Bradley Blevins	Date and Hour: 12/13/14 at approximately 4:00 p.m. <b>3:25 PM</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

**15 2014**

**RECEIVED**

Describe Cause of Problem and Remedial Action Taken.\*  
A flex gasket on the wellhead failed releasing produced water on the well pad. All of the free standing fluid was recovered and the gasket was replaced.

Describe Area Affected and Cleanup Action Taken.\*  
The spill impacted approximately 15,300 sq.ft. of caliche well pad and approximately 4,000 sq.ft. pasture area. The impacted area was left as is pending final remediation. There was a significant area of produced water impact on the well pad prior to the release that was scheduled to be cleaned up due to the possible construction of a SWD facility on the well pad.  
The spill area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie		Approved by Environmental Specialist <u>Mike Bratcher</u>	
Title: Waste Management and Remediation Specialist		Approval Date: <u>12/16/14</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>tasavoie@basspet.com</u>		Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b>	
Date: <u>12/15/14</u> Phone: <u>432-556-8730</u>		Attached <input type="checkbox"/> <b>SUBMIT REMEDIATION PROPOSAL NO.</b>	

**LATER THAN: 11/10/15**

**2RP-2463**

\* Attach Additional Sheets If Necessary