

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

JAN 06 2015 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1501 255875

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <i>260131</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU-29 SWD Tank Battery, on the Pad with the producing well.	Facility Type: Exploration and Production

Surface Owner: State of N.M.	Mineral Owner: State of N.M.	API No. 30-015-27735
------------------------------	------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County:
K	36	22S	30E	1980	South	2310	West	Eddy

Latitude N 32.346493 Longitude W 103.835563

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 97 bbls.	Volume Recovered: 3 bbls.
Source of Release: Unknown truck dumped fluid or left the truck load line valve open.	Date and Hour of Occurrence: 12/25/14 Time unknown	Date and Hour of Discovery: 12/25/14 at about 5:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The produced water was assumed to have come from BOPCO operations but has not been confirmed. The spill was a result of an unknown truck driver failed to control fluids while unloading or parked at the BOPCO SWD Tank Battery. An investigation is underway. Attached is a record of events and findings to-date.

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 14,500 sq.ft. of Tank Battery/well pad. A vacuum truck recovered approximately 3 bbls of fluid upon discovery. The pad area had a significant rain event after the release and prior to EH&S site review. The spill area will be cleaned up in accordance to the NMOCD remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Signed By <i>Mike Scanlon</i> Approved by Environmental Specialist:	
Title: Waste Management and Remediation Specialist	Approval Date: <i>1/12/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>2/12/15</i>	
Date: 1/6/15	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

2RP-2726