

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

NAB1501 242084		10696		<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: OXY Permian				Contact: Christopher Jones			
Address: 1502 W Commerce Dr.				Telephone No. 575-499-3337			
Facility Name: Gaines 22 Fed 1 CTB				Facility Type: Battery			

Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-35186
--------------------	--------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section: 22	Township: 22S 24S	Range: 29E	Feet from the 820	North/South Line South	Feet from the 590	East/West Line West	County Eddy
-------------	-------------	----------------------	------------	-------------------	------------------------	-------------------	---------------------	-------------

Latitude 32.197975 Longitude 103.97768922

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release: 150BBLS	Volume Recovered: 60BBLS
Source of Release: Heater	Date and Hour of Occurrence: 12/18/2014 7:00	Date and Hour of Discovery: 12/18/2014 7:30AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry Bratcher	
By Whom? Jorge Calleros	Date and Hour 12/18/2014 8:30AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**NM OIL CONSERVATION**

ARTESIA DISTRICT

JAN 06 2015

Describe Cause of Problem and Remedial Action Taken.\*


Well is down and circulating pump was running causing fluid to go to heater treater so valve relieved.

RECEIVED

Describe Area Affected and Cleanup Action Taken.\*

Safety & Environmental Solutions, Inc. will delineate the spill area and submit an appropriate work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones	Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones888@yahoo.com, c=US Date: 2014.12.29 12:59:59 -06'00'		<b>OIL CONSERVATION DIVISION</b>	
Printed Name Christopher Jones:	Approved by Environmental Specialist:			
Title:	Approval Date: 1/12/14	Expiration Date:		
E-mail Address: Christopher_jones@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 12/19/2014	Phone: 575-499-3337			

\* Attach Additional Sheets If Necessary

2BP-2722