

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

Form C-141
Revised October 10, 2003

JAN 15 2015
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

0AB1502037424

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company : Oxy Permian LTD (192463)	Contact : Chris Jones
Address : 1502 W. Commerce, Carlsbad, NM 88220	Telephone No. : 575-628-4121
Facility Name : North Burton Flats Battery (Government AA #2)	Facility Type: Central Tank Battery

Surface Owner : Federal	Mineral Owner	API#: 30-015-33283 Lease No.: NM 18293
--------------------------------	---------------	---

LOCATION OF RELEASE

Unit Letter D	Section 23	Township 20S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy, NM
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-------------------------

Latitude **32.5658815 N** Longitude **-104.1557648 W**

NATURE OF RELEASE

Type of Release : Oil	Volume of Release : 15 bbls	Volume Recovered: 10 bbls
Source of Release : Gas Supply Line	Date and Hour of Occurrence: 1/5/2015	Date and Hour of Discovery: 1/6/2015 11:19 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD/Mike Bratcher via telephone BLM/Jim Amos via email	
By Whom: Kimberly M. Wilson	Date and Hour : 1/8/2015 10:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A gas supply line froze and lost pressure sending the fluid to the field vent releasing 15 barrels of oil. The facility was shut-in and the gas line repaired. A vac truck was immediately called to the location and recovered 10 barrels of oil.

Describe Area Affected and Cleanup Action Taken.* The area impacted measured approximately 20'x12' inside the containment. The oil breached the berms and impacted approximately 25'x15 onto the location. Talon/LPE has been contracted to complete site assessment and remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones		OIL CONSERVATION DIVISION	
Printed Name: Chris Jones		Approved by District Supervisor: 	
Title: HES Specialist		Approval Date: 1/14/15	Expiration Date: NA
E-mail Address: Christopher_Jones@oxy.com		Conditions of Approval:	
Date: 1/9/2015 Phone: 575-628-4121		Attached <input type="checkbox"/>	

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO.
LATER THAN: **2/16/15**

* Attach Additional Sheets If Necessary

2RP-2745