

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

NAB15020210861 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Burnett Oil Co., Inc.	Contact Leslie Garvis
Address 801 Cherry Street - Suite 1500, Ft. Worth, TX 76102	Telephone No. 817-583-8730
Facility Name Gissler B 88	Facility Type Oil Well

Surface Owner BLM	Mineral Owner BLM	API No. 30-015-40847
-------------------	-------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	11	17S	30E	1650	South	330	East	Eddy

Latitude 32.8463087 Longitude 103.9351954

**NATURE OF RELEASE**

Type of Release Water/Oil	Volume of Release 100/20	Volume Recovered 85/10
Source of Release Pumping Unit	Date and Hour of Occurrence 1/16/15	Date and Hour of Discovery 1/16/15 1600
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM-Robertson / OCD-Patterson/ Email notification on 1/17/15	
By Whom? Johnny Titworth - Burnett	Date and Hour 1/16/15 approx 1615	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*

N/A

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

JAN 19 2015

Describe Cause of Problem and Remedial Action Taken.\*

Liner on polish rod slipped. Liner was reattached and bolts tightened.

RECEIVED

Describe Area Affected and Cleanup Action Taken.\*

Majority of the release stayed on the location pad. Some flowed to the SW corner of the location and a nearby pasture. The pasture area affected was approximately 30'x50'. All standing fluid was vacuumed up. The pad and the pasture will be assessed and remediated according to BLM & NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Leslie Garvis</u>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Leslie Garvis		Approved by Environmental Specialist: <u>Hu</u>	
Title: Regulatory Coordinator		Approval Date: <u>1/20/15</u>	Expiration Date: <u>NA</u>
E-mail Address: <u>lgarvis@burnettoil.com</u>		Conditions of Approval:	
Date: 1/19/16 Phone: 817-332-5108		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-2743