

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

JAN 26 2015  
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1502727312		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P.		Contact: Tony Savoie			
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329			
Facility Name: PLU-158 Tank Battery		Facility Type: Exploration and Production			
Surface Owner: Federal		Mineral Owner: Federal		API No. 30-015-31690	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	7	24S	30E	660	North	660	East	Eddy

Latitude N 32.237661 Longitude W 103.913889

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 27 bbls crude oil and 8 bbls produced water	Volume Recovered: 20 bbls crude oil and 4 bbls produced water
Source of Release: Heater-treater	Date and Hour of Occurrence: 1/23/15 time unknown	Date and Hour of Discovery: 1/23/15 approx. 10:35 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher, H. Patterson, and Jim Amos	
By Whom? Tony Savoie	Date and Hour: 1/23/15 at 12:52 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A gasket failed on the heater-treater fire tube. The heater was by-passed and the gasket was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The spill impacted approximately 2100 sq.ft. of tank battery caliche containment area and approximately 250 sq. ft. of pasture was misted with crude oil. There was no vegetation in the pasture area impacted. A vacuum truck recovered the free standing fluids. The stained area was left as is pending the final remediation.

The area will be cleaned up in accordance with the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Signed By: <u>Mike B. Davidson</u>	
Title: Waste Management and Remediation Specialist		Approved by Environmental Specialist:	
E-mail Address: tasavoie@basspet.com		Approval Date: <u>1/27/15</u>	Expiration Date: <u>N/A</u>
Date: <u>1/26/15</u>	Phone: 432-556-8730	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
SUBMIT REMEDIATION PROPOSAL NO			

\* Attach Additional Sheets If Necessary

LATER THAN: 2/27/15

2RP-2762