

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

Operator ☒ Initial Report ☐ Final Report

Name of Company RKIE&P, LLC **Contact** Taylor Jones
Address 210 Park Ave. - Ste. 900, OKC, OK 73102 **Telephone No.** 405-996-5782
Facility Name: Brushy Creek Gathering Station **Facility Type:** Tank Battery

Surface Owner Federal **Mineral Owner** NA **API No.** 30-015-24451

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	25	26S	29E		660 FSL		1980FWL	Eddy

Latitude: 32.007240348386 **Longitude:** -103.940095327473

NATURE OF RELEASE

Type of Release: Produced Water/Oil	Volume of Release: 10il/10water Bbls	Volume Recovered: 0oil/10water Bbls
Source of Release: Tanks overran	Date and Hour of Occurrence 01/22/15 - prior to 0800hrs MT	Date and Hour of Discovery 01/22/15 - 0800hrs MT
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

NM OIL CONSERVATION
ARTESIA DISTRICT

Describe Cause of Problem and Remedial Action Taken.*

FEB 05 2015

More water was put into system and trucking company failed to haul sufficient loads away.

RECEIVED

Shut in wells and let station pump down. Had vac truck within 1 hour to suck up water out of containment.

Describe Area Affected and Cleanup Action Taken.*

All fluid remained in secondary containment berm, 10/11Bbls spilled were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Taylor Jones</i>	OIL CONSERVATION DIVISION	
Printed Name: Taylor Jones	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: EHS Systems Specialist	Approval Date: 2/9/15	Expiration Date:
E-mail Address: TJones@rkxp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 02/05/15 Phone: 405-996-5782	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 3/9/15

2RP-2796